



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME PARKVIEW APARTMENTS				REINSPECTION DATE Not Specified	INSPECTOR Kelly Eredia	DATE 6/29/2016
LOCATION 16350 PEBBLE BEACH DR, VICTORVILLE, CA 92392				PERMIT EXPIRATION 10/31/2016	IDENTIFIER: Pool	
TIME IN 5:11 PM	TIME OUT 5:29 PM	FACILITY ID FA0005358	RELATED ID PR0015756	PE 3620	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
				RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED		
				ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN		

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	70
volume (gal)	34,000
area (sq ft)	800
occupancy	40

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: Permit reinstated due to vacless SVRS system provided.

Description: The health permit to operate is hereby reinstated and facility may open.

Overall Inspection Comments

Permit reinstated due to correction of main drain suction hazard.

Signature(s) of Acknowledgement

NAME: SNA
TITLE:

Total # of Images: 0