



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW
REPORT**

www.sbcounty.gov/dehs

FACILITY NAME RESIDENCE INN OF SAN BERNARDINO				DATE 12/4/2012	SIGNATURE
LOCATION 1040 E HARRIMAN PL, SAN BERNARDINO, CA 92408				REINSPECTION DATE Not Specified	PERMIT EXPIRATION
MAILING ADDRESS Not Specified				REHS Kathy Taylor	
FA # FA0014705	PR # Not Specified	SR # SR0057688	CO # Not Specified	PE 3716	PROGRAM IDENTIFIER: None
TIME IN 1:15 PM	TIME OUT 2:00 PM	CONTACT Not Captured			SERVICE: 025 - Plan Review
				RESULT: 01 - Corrective Action Not Required	ACTION: 55 - Plans Approved

RECREATIONAL HEALTH PLAN CHECK - PLNCK POOL MINOR REMODEL - ALL

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50

Observations

Plan Check Information - Type of inspection and/or status of review

1. Plans - Plan Review Approved

Compliance Date not Specified *Violation Description:* Plans have been approved and this correction sheet is a part of the approved plans.

Not In Compliance *Inspector Comments:*

Violation Reference: HSC

Observation Violations

2. Equipment - Disinfection - Auto

Compliance Date not Specified *Violation Description:* An approved automatic disinfectant feeder is required.

Not In Compliance *Inspector Comments:*

Violation Reference: CCR 24 - 3123B.1

Overall Inspection Comments

Plans have been received for the installation of a CPSC salt water chlorination system (NSF approved) for the spa.

The spa must have an automatic chlorination system in place capable of delivering a continuous supply of chlorine at a rate of 3 lbs per 10,000 gallons of water in a 24 hour period.

This means the spa must keep it's originally-approved automatic chlorinator plumbed into the system.

The presence of the salt water chlorination system does not eliminate the requirement for the original chlorinator.

NOTE: The turnover rate for the spa must remain at a minimum of 36 gallons per minute; the additional plumbing may not impair the minimum flow rate.

Call for inspection when ready; call at least one week in advance at 1-800-442-2283.

Thank you

NOTE: Pool turnover rate is 40 gpm.