



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME YUCCA VALLEY HIGH SCHOOL					DATE 8/1/2013	SIGNATURE	
LOCATION 7600 SAGE AV, YUCCA VALLEY, CA 92284					REINSPECTION DATE 2/01/2014	PERMIT EXPIRATION	
MAILING ADDRESS 7600 SAGE AV, YUCCA VALLEY, CA 92284					REHS Dior Porter		
FA # FA0006734	PR # PR0014801	SR # Not Specified	CO # Not Specified	PE 3603	PROGRAM IDENTIFIER: None		
TIME IN 2:05 PM	TIME OUT 2:30 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

RECREATIONAL HEALTH - PUBLIC SCHOOL POOL / SPA




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

98

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	600
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K440 Enclosure - Non-Critical - Enclosure/Gates Non-Drowning Hazard

POINTS
2

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - HSC - 3119B

Inspector Comments: Observed gate not self latching. Repair. (lifeguard present at all times, permit not suspended per Leilah K.)

Violation Description: The enclosure, doors and gates shall meet all requirements in the California Code of Regulations. Fencing/gates shall be maintained in good repair.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:

No Photo Attachments