



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

FACILITY NAME <b>REDLANDS HIGH SCHOOL</b>				DATE <b>8/27/2013</b>	SIGNATURE	
LOCATION <b>840 E CITRUS AV, REDLANDS, CA 92373</b>				REINSPECTION DATE <b>2/27/2014</b>	PERMIT EXPIRATION	
MAILING ADDRESS <b>840 E CITRUS AV, REDLANDS, CA 92373</b>				<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT REHS <b>Eurich Santiago</b>		
FA # <b>FA0006492</b>	PR # <b>PR0014836</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3603</b>	PROGRAM IDENTIFIER: Shallow Pool	
TIME IN <b>11:07 AM</b>	TIME OUT <b>11:30 AM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - Inspection - Routine	
					RESULT: 03 - Corrective Action / No Follow up Required	
					ACTION: 01 - No Further Action Required	

**RECREATIONAL HEALTH - PUBLIC SCHOOL POOL / SPA**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**98**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	402
required flow (gpm)	360
volume (gal)	129,938
area (sq ft)	3,850
occupancy	192

**36K472 Access - Steps - Handrails - Diving Area**

**POINTS**  
**2**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - CCR - 3111B,  
 3113B

**Inspector Comments:** Observed loose handrails at pool area. Ensure all handrails are tightly fitted.

**Violation Description:** Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**  
 No Photo Attachments