



Public Health
Environmental Health Services



www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME HOLIDAY INN		DATE 5/11/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 1/31/2016
LOCATION 2155 E CONVENTION CENTER WY, ONTARIO, CA 91764			INSPECTOR John Ramos	
MAILING ADDRESS 2155 E CONVENTION CENTER WY, ONTARIO CA 91764			IDENTIFIER: Pool	
TIME IN 10:52 AM			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME OUT 11:07 AM			RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
FACILITY ID FA0016023			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	
RELATED ID PR0021307				
PE 3620				

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	21,368
area (sq ft)	695
occupancy	34

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Comply by: 5/11/2015	Inspector Comments: Permit is hereby reinstated. A reinspection was conducted to determine compliance with a previously observed violation. Pool is reopened.
	Complied on 5/11/2015	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

POINTS NA	Comply by: 5/11/2015	Inspector Comments: A pool reinspection was conducted to determine compliance with a previously observed violation. Observed GFCI repaired. Pool reopened.
	Complied on 5/11/2015	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

Permit is hereby reinstated. A reinspection was conducted to determine compliance with a previously observed violation. Pool is reopened.

Signature(s) of Acknowledgement

NAME:
TITLE:
Total # of Images: 0