



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

RETAIL FOOD PROTECTION - OFFICIAL INSPECTION REPORT

FACILITY NAME ROUND TABLE PIZZA				REINSPECTION DATE Not Specified	INSPECTOR Kelly Eredia	DATE 3/22/2022
LOCATION 14898 DALE EVANS PKWY 200, APPLE VALLEY, CA 92307				PERMIT EXPIRATION	IDENTIFIER: None	
TIME IN 9:58 AM	TIME OUT 10:35 AM	FACILITY ID FA0016195	RELATED ID CO0082544	PE 1622	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	

RETAIL FOOD PROTECTION - Public Eating PI (100-Up Seats)

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

16K992 Permit Reinstatement

Compliance Date: Not Specified

Inspector Comments: Permit reinstated due to elimination of sewage overflow.

Not In Compliance

Reference - HSC

Description: The health permit to operate is hereby reinstated and facility may open.

16K994 Reinspection

Compliance Date: Not Specified

Inspector Comments: Reinspection conducted on this day as a follow-up to complaint investigation conducted 3/21/22. On that day, Environmental Health received a complaint on 3/21/2022 stating there is a sewage overflow in the parking lot. On that day permit was suspended and facility closed due to active sewage overflow observed in parking lot. Facility was advised to service and clean grease receptors, and to remain closed until reinspected by EHS once sewage overflow has been eliminated.

During complaint investigation conducted 3/21/22, plumber arrived and stated that the grease interceptors will be jettied, however, they will not be cleaned. An additional service technician is required for cleaning grease receptors. Owner stated grease receptors were scheduled to be clean at 7AM on 3/22/22.

During follow-up inspection, sewage overflow was observed eliminated. Invoice for plumber observed dated 3/21/22 and invoice for grease trap indicating 1200 gallons were pumped from grease trap with hydrojetting.

During follow-up to complaint, no active sewage overflow was observed.

No further action required at this time. Permit reinstated.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

Reinspection conducted on this day. Permit reinstated due to elimination of sewage overflow. "Notice of Closure" sign removed; "A" grade placard reposted.

FREE Classes to L.E.A.R.N!

Liaison Education And Risk Network (L.E.A.R.N.) is a FREE class based on the fundamentals of Active Managerial Control and the Centers for Disease Control and Prevention's five risk factors that lead to foodborne illnesses. Find out when the next L.E.A.R.N. class is by checking our [calendar](#).

Signature(s) of Acknowledgement

No Sig

NAME: Sam Sandhu
TITLE: Owner

Total # of Images: 0