



**Public Health**  
Environmental Health Services

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>BEST WESTERN BIG BEAR CHATEAU</b>		DATE <b>5/29/2015</b>	REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION <b>11/30/2015</b>
LOCATION <b>42200 MOONRIDGE RD, BIG BEAR LAKE, CA 92315</b>			INSPECTOR <b>Sierra Clayborn</b>	
MAILING ADDRESS <b>PO BOX 1814, BIG BEAR LAKE CA 92315</b>			IDENTIFIER: Spa	
TIME IN <b>5:05 PM</b>			SERVICE: 001 - INSPECTION - ROUTINE	
TIME OUT <b>5:35 PM</b>			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
FACILITY ID <b>FA0005560</b>			ACTION: 01 - NO FURTHER ACTION REQUIRED	
RELATED ID <b>PR0015803</b>			PE <b>3623</b>	




**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**93**  
SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (°F)	103.6
observed flow (gpm)	No Data
required flow (gpm)	25
volume (gal)	750
area (sq ft)	50
occupancy	5

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K504 Water Quality – Non-Critical – Disinfectant level low**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	Inspector Comments: Observed spa free chlorine at 2.48ppm.
	Not In Compliance	Ensure that free chlorine in a spa is maintained between 3.0ppm and 10ppm.
	Violation Reference - HSC - 65529	

**Violation Description:** The minimum concentration of disinfectant residual in public pools shall be 1.0 ppm free-chlorine without cyanuric acid or 2.0 ppm free-chlorine with cyanuric acid. The minimum concentration of disinfectant residual in public spas, wading pools, and spray grounds shall be 3.0 ppm free-chlorine. The maximum concentration of disinfectant residual shall be 10.0 ppm free-chlorine.

The minimum concentration of bromine residual in public pools shall be 2.0 ppm. The minimum concentration of bromine residual in public spas, wading pools, and spray grounds shall be 4.0 ppm.

**36K518 Water Quality – Cyanuric acid concentration**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	Inspector Comments: Observed cyanuric acid high, exceeding 100ppm.
	Not In Compliance	
	Violation Reference - HSC - 65530	

**Violation Description:** The maximum concentration of cyanuric acid in public pool water shall not exceed 100.0 ppm.



## Public Health

### Environmental Health Services

[www.SBCounty.gov](http://www.SBCounty.gov)

### RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME BEST WESTERN BIG BEAR CHATEAU	DATE 5/29/2015
LOCATION 42200 MOONRIDGE RD, BIG BEAR LAKE, CA 92315	INSPECTOR Sierra Clayborn

#### IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

#### 36K527 Safety – Safety signs

POINTS <b>1</b>	Compliance Date: Not Specified	Inspector Comments: Observed diarrhea advisory sign not easily readable from entrance of spa enclosure.  Relocate diarrhea advisory sign so that it is clearly readable from the entrance.
	Not In Compliance Violation Reference - CCR - 3120B	

**Violation Description:** All signs shall have clearly legible letters or numbers not less than 4 inches high, unless otherwise required, affixed to a wall, pole, gate or similar permanent structure in a location visible to all pool users. The following shall be posted:

- a) Maximum number of pool users permitted for each pool.
- b) "NO DIVING" at pools with a maximum water depth of 6 feet or less.
- c) Where no lifeguard service is provided, a warning sign shall be posted stating, "WARNING: NO LIFEGUARD ON DUTY." The sign also shall state in letters at least 1 inch high, "Children under the age of 14 shall not use pool without a parent or adult guardian in attendance."
- d) An illustrated diagram with text at least 1/4 inch high of artificial respiration and CPR procedures.
- e) The emergency telephone number 911 with numbers not less than 4 inches (102mm), the number of the nearest emergency services and the name and street address of the pool facility with numbers and text not less than 1 inch (25 mm) shall be posted.
- f) A warning sign for spa pools with "CAUTION" language.
- g) Where pools were constructed for which lighting was not required, a sign shall be posted at each pool entrance on the outside of the gate(s) stating, "NO USE OF POOL ALLOWED AFTER DARK."
- h) A sign shall be posted on the exterior side of gates and doors leading into the pool enclosure area stating, "KEEP GATE CLOSED" or "KEEP DOOR CLOSED".
- i) A sign in letters at least 1 inch high and in a language or diagram that is clearly stated shall be posted at the entrance area of a public pool which states that persons having currently active diarrhea or who have had active diarrhea within the previous 14 days shall not be allowed to enter the pool water.
- j) A sign in letters at least 1 inch high shall be posted that describes the requirements for wave pools.
- k) A sign shall be posted at each spray ground and be visible from any part of the spray ground that states, "CAUTION: WATER IS RECIRCULATED. DO NOT DRINK."

#### 36K552 Equipment - Flow meter provided

POINTS <b>1</b>	Compliance Date: Not Specified	Inspector Comments: Observed no flow meter installed on recirculation plumbing.  Provide.
	Not In Compliance Violation Reference - CCR 24 - 3125B.3	

**Violation Description:** A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow and installed according to the manufacturer's written instructions with increments in the range of normal flow.

#### 36K562 Skimmers - Pool skimming systems

POINTS <b>1</b>	Compliance Date: Not Specified	Inspector Comments: Observed float assembly missing from skimmer.  Replace.
	Not In Compliance Violation Reference - CCR - 3136B	

**Violation Description:** The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 100 percent of the flow rate. Each surface skimmer shall comply with the requirements in accordance with section 3136B, Title 24, California Code of Regulations.

#### 36K566 Lighting – Requirements

POINTS <b>1</b>	Compliance Date: Not Specified	Inspector Comments: Observed light control panel unmarked and lights not turning on in pool or spa during inspection.  Ensure that pool/spa underwater lights function properly and that they are coordinated with a properly functioning GFCI. Ensure that lighting panel is labeled.
	Not In Compliance Violation Reference - CCR - 3115B	

**Violation Description:** Pools shall have underwater and deck lighting such that lifeguards or other persons may observe, without interference from direct and reflected glare from the lighting sources, every part of the underwater area and pool surface, all diving boards or other pool appurtenances.



**Public Health**  
**Environmental Health Services**

www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>BEST WESTERN BIG BEAR CHATEAU</b>	DATE <b>5/29/2015</b>
LOCATION <b>42200 MOONRIDGE RD, BIG BEAR LAKE, CA 92315</b>	INSPECTOR <b>Sierra Clayborn</b>

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K597 Construction - Pool shell tiles and surface**

<b>POINTS</b>  <b>1</b>	<b>Compliance Date:</b> Not Specified	<b>Inspector Comments:</b> Observed spa shell stained blue. Maintenance assistant on site stated that the old heater had some recent issues and was replaced.
	<b>Not In Compliance</b>	
	<b>Violation Reference - CCR - 3108B</b>	

**Violation Description:** The finished pool shell shall be lined with a smooth waterproof interior finish that will withstand repeated brushing, scrubbing and cleaning procedures. The interior pool finish shall completely line the pool to the tile lines, coping, or cantilevered deck.

- The finish color shall be white except for the following which shall be of contrasting color:
1. Lane and other required pool markings described in Section 3110B of the California Code of Regulations; and
  2. The top surface edges of benches in spa pools; and
  3. The edge of pool steps; and
  4. Tiles installed at the waterline; and
  5. Tiles installed at the 4 1/2-foot (1372 mm) depth line.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME:  
 TITLE:  
 Total # of Images: 0