





Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME WOODLANDS HOA		DATE 7/6/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2016
LOCATION 1965 E COULSTON ST, LOMA LINDA, CA 92354			INSPECTOR Veronica Vazquez	
MAILING ADDRESS 12345 MOUNTAIN AV STE N-239, CHINO CA 91710			IDENTIFIER: Spa	
TIME IN 1:35 PM	TIME OUT 2:10 PM	FACILITY ID FA0008320	RELATED ID PR0014112	PE 3623
			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	7

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Spa is hereby open.
	Not In Compliance	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Observed free chlorine at 5 ppm in spa water. Spa is hereby open. Removed closure sign.
	Not In Compliance	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

36K542 Enclosure – Non-Critical – Gates and doors self-closing and self-latching

POINTS 1	Comply by: 7/8/2015	Inspector Comments: Repair/replace east spa/ pool gate. Observed pool gate not self latching. Closed pool gate with zip tie.
	Not In Compliance	
	Violation Reference - CCR - 3119B	

Repair/replace west spa/pool gate. Observed key not opening gate to exit spa/pool area. Will reinspect.

Facility has north spa/pool gate self closing and latching and serves as a keyless emergency exit.

Violation Description: Gates and doors shall be equipped with self-closing and self-latching devices. Gates and doors shall be capable of being locked during times when the pool is closed. The self-latching device shall keep the gate or door securely closed. Gates and doors shall open outwardly away from the pool except where otherwise prohibited by law. The pool enclosure shall have at least one means of egress without a key for emergency purposes. The enclosure shall be constructed so that all persons will be required to pass through common pool enclosure gates or doors in order to gain access to the pool area. All gates and doors exiting the pool area shall open into a public area or a walkway accessible by all patrons of the pool.

Overall Inspection Comments

Will reinspect west/east gate are repaired.

Call Veronica Vazquez at (800) 442-2283 with questions.

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME WOODLANDS HOA	DATE 7/6/2015
LOCATION 1965 E COULSTON ST, LOMA LINDA, CA 92354	INSPECTOR Veronica Vazquez

NAME:
TITLE:

Total # of Images: 0