



**Public Health**  
Environmental Health Services

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

|  |                             |                                 |  |                                       |
|--|-----------------------------|---------------------------------|--|---------------------------------------|
| FACILITY NAME<br><b>RED ROOF INN</b>   |                             | DATE<br><b>6/8/2015</b>         | REINSPECTION DATE<br><b>Not Specified</b>        | PERMIT EXPIRATION<br><b>6/30/2015</b> |
| LOCATION<br><b>13409 MARIPOSA RD, VICTORVILLE, CA 92392</b>  |                             |                                 | INSPECTOR<br><b>Patrick Baccari</b>              |                                       |
| MAILING ADDRESS<br><b>106 CITRUS RANCH RD, SAN DIMAS CA 91773</b>  |                             |                                 | IDENTIFIER: North Spa                            |                                       |
| <input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT |                             |                                 | SERVICE: 001 - INSPECTION - ROUTINE              |                                       |
| TIME IN<br><b>10:00 AM</b>   | TIME OUT<br><b>10:30 AM</b> | FACILITY ID<br><b>FA0004486</b> | RELATED ID<br><b>PR0013927</b>                   | PE<br><b>3623</b>                     |
|  |                             |                                 | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE |                                       |
|  |                             |                                 | ACTION: 01 - NO FURTHER ACTION REQUIRED          |                                       |



**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**91**  
SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

|                   |
|-------------------|
| Ideal             |
| In Compliance     |
| Not in Compliance |



|                     |         |
|---------------------|---------|
| temperature (°F)    | 98.0    |
| observed flow (gpm) | No Data |
| required flow (gpm) | 27      |
| volume (gal)        | 809     |
| area (sq ft)        | 50      |
| occupancy           | 5       |

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K502 Water Quality - Critical – Disinfectant level** ⚠ CRITICAL ⚠

|                           |                                   |  |
|---------------------------|-----------------------------------|--|
| <b>POINTS</b><br><b>5</b> | Compliance Date: Not Specified    | Inspector Comments: Initial test for chlorine resulted in 0.00. Liquid chlorine was added to spa resulted in 6.58 ppm free available chlorine. |
|                           | Not In Compliance                 |  |
|                           | Violation Reference - HSC - 65529 |  |

**Violation Description:** The minimum concentration of disinfectant residual in public pools shall be 1.0 ppm free-chlorine without cyanuric acid or 2.0 ppm free-chlorine with cyanuric acid. The minimum concentration of disinfectant residual in public spas, wading pools, and spray grounds shall be 3.0 ppm free-chlorine. The maximum concentration of disinfectant residual shall be 10.0 ppm free-chlorine.

The minimum concentration of bromine residual in public pools shall be 2.0 ppm. The minimum concentration of bromine residual in public spas, wading pools, and spray grounds shall be 4.0 ppm.

A spray ground and water features with an ultraviolet light disinfection system shall be disinfected continuously at a minimum of 40 mJ/cm2 by the ultraviolet light disinfection units while the spray ground and water features are in use. If the ultraviolet dosage rate drops below 40 mJ/cm2 the operator shall close the spray ground and water features.

**36K526 Safety - Emergency shut-off switch**

|                           |  |  |
|---------------------------|--|--|
| <b>POINTS</b><br><b>1</b> | Compliance Date: Not Specified         | Inspector Comments: A clearly labeled emergency shut off switch for the control of both the recirculation system and the aeration and/or jet system shall be installed adjacent to the spa pool. An emergency shut off switch sign is missing. |
|                           | Not In Compliance                      |  |
|                           | Violation Reference - CCR 24 - 3138B.5 |  |

**Violation Description:** A clearly labeled emergency shut off switch for the control of both the recirculation system and the aeration and/or jet system shall be installed adjacent to the spa pool.



## Public Health

### Environmental Health Services

[www.SBCounty.gov](http://www.SBCounty.gov)

### RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

|   |                                     |
|---|-------------------------------------|
| FACILITY NAME<br><b>RED ROOF INN</b>                        | DATE<br><b>6/8/2015</b>             |
| LOCATION<br><b>13409 MARIPOSA RD, VICTORVILLE, CA 92392</b> | INSPECTOR<br><b>Patrick Baccari</b> |

#### IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

#### 36K527 Safety – Safety signs

|                    |                                   |   |
|--------------------|-----------------------------------|---|
| POINTS<br><b>1</b> | Compliance Date: Not Specified    | Inspector Comments: Provide the number of the nearest emergency services.<br><br>And provide the name and street address of the pool facility.<br><br>A sign shall be posted on the exterior side of gates and doors leading into the pool enclosure area stating, ""KEEP GATE CLOSED"" or ""KEEP DOOR CLOSED"".<br><br>A sign in letters at least 1 inch high and in a language or diagram that is clearly stated shall be posted at the entrance area of a public pool which states that persons having currently active diarrhea or who have had active diarrhea within the previous 14 days shall not be allowed to enter the pool water. |
|                    | Not In Compliance                 |   |
|                    | Violation Reference - CCR - 3120B |   |

**Violation Description:** All signs shall have clearly legible letters or numbers not less than 4 inches high, unless otherwise required, affixed to a wall, pole, gate or similar permanent structure in a location visible to all pool users. The following shall be posted:

- a) Maximum number of pool users permitted for each pool.
- b) ""NO DIVING"" at pools with a maximum water depth of 6 feet or less.
- c) Where no lifeguard service is provided, a warning sign shall be posted stating, ""WARNING: NO LIFEGUARD ON DUTY."" The sign also shall state in letters at least 1 inch high, ""Children under the age of 14 shall not use pool without a parent or adult guardian in attendance.""
- d) An illustrated diagram with text at least 1/4 inch high of artificial respiration and CPR procedures.
- e) The emergency telephone number 911 with numbers not less than 4 inches (102mm), the number of the nearest emergency services and the name and street address of the pool facility with numbers and text not less than 1 inch (25 mm) shall be posted.
- f) A warning sign for spa pools with ""CAUTION"" language.
- g) Where pools were constructed for which lighting was not required, a sign shall be posted at each pool entrance on the outside of the gate(s) stating, ""NO USE OF POOL ALLOWED AFTER DARK.""
- h) A sign shall be posted on the exterior side of gates and doors leading into the pool enclosure area stating, ""KEEP GATE CLOSED"" or ""KEEP DOOR CLOSED"".
- i) A sign in letters at least 1 inch high and in a language or diagram that is clearly stated shall be posted at the entrance area of a public pool which states that persons having currently active diarrhea or who have had active diarrhea within the previous 14 days shall not be allowed to enter the pool water.
- j) A sign in letters at least 1 inch high shall be posted that describes the requirements for wave pools.
- k) A sign shall be posted at each spray ground and be visible from any part of the spray ground that states, ""CAUTION: WATER IS RECIRCULATED. DO NOT DRINK.""

#### 36K548 Equipment - General Requirements - System Description

|                    |  |   |
|--------------------|--|---|
| POINTS<br><b>1</b> | Compliance Date: Not Specified         | Inspector Comments: Replace missing flow meter.<br><br>Connect bond wire where missing from motors.<br><br>Air jets to spa need to be repaired. |
|                    | Not In Compliance                      |   |
|                    | Violation Reference - CCR 24 - 3123B.1 |   |

**Violation Description:** Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The system shall consist of pumps, filters, chemical feeders, skimmers or perimeter overflow systems, valves, pipes, connections, fittings and appurtenances.

#### 36K576 Maintenance – Operation/Incident records

|                    |                                   |   |
|--------------------|-----------------------------------|---|
| POINTS<br><b>1</b> | Compliance Date: Not Specified    | Inspector Comments: The pool operator shall maintain a written daily record of all test results, equipment readings, calibrations, and corrective action taken at the public pool site. [This includes daily records of pH, disinfectant level, and water temperature. This is for each pool, spa.] |
|                    | Not In Compliance                 |   |
|                    | Violation Reference - HSC - 65523 |   |

**Violation Description:** The pool operator shall maintain a written daily record of all test results, equipment readings, calibrations, and corrective action taken at the public pool site. [This includes daily records of pH, disinfectant level, and water temperature. If used, cyanuric acid concentration shall be tested monthly.]

If a fecal, vomit, blood contamination, near-drowning, or drowning incident occurs in a pool, the pool operator shall record the incident in accordance with the requirements of [Health and Safety Code] section 65546 and shall identify the affected public pool in the incident record if there is more than one pool at the public pool site. This record shall be maintained at the public pool site.

#### Overall Inspection Comments



**Public Health**  
Environmental Health Services

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

|  |                              |
|--|------------------------------|
| FACILITY NAME<br>RED ROOF INN                        | DATE<br>6/8/2015             |
| LOCATION<br>13409 MARIPOSA RD, VICTORVILLE, CA 92392 | INSPECTOR<br>Patrick Baccari |

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME: Sandra leija  
TITLE:

Total # of Images: 0