



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME RED ROOF INN		REINSPECTION DATE Not Specified		INSPECTOR Melissa Nano	DATE 10/28/2015
LOCATION 13409 MARIPOSA RD, VICTORVILLE, CA 92392				PERMIT EXPIRATION 6/30/2016	IDENTIFIER: Pool
TIME IN 4:17 PM	TIME OUT 4:32 PM	FACILITY ID FA0004486	RELATED ID PR0013926	PE 3620	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION
					RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED
					ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN



RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	59
volume (gal)	21,340
area (sq ft)	634
occupancy	32

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: The pool health permit is hereby reinstated for meeting compliance from a previous violation observed during prior routine inspection. Pool facility may reopen and operate.
	Not In Compliance	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: A re-inspection was conducted to verify compliance from a prior inspection. Previously, Observed water in underwater light fixture causing an unknown electrical hazard. Observed no water in light fixture at re-inspection. Operator states they have also replaced gasket so that water no longer enters fixture. Pool may re-open.
	Not In Compliance	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

Pool facility has been reinspected and verified for compliance. Pool facility may reopen.

If there are any questions, please contact Environmental Health Services or Melissa Nano at (800) 442-2283.

Signature(s) of Acknowledgement

NAME: Stephanie Berger
TITLE:



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME RED ROOF INN	DATE 10/28/2015
LOCATION 13409 MARIPOSA RD, VICTORVILLE, CA 92392	INSPECTOR Melissa Nano

Total # of Images: 0