



Public Health
Environmental Health Services




www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME LOMA LINDA VILLAGE HOA		DATE 6/10/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 3/31/2015
LOCATION 10196 AMBROSIA WY, SAN BERNARDINO, CA 92408			INSPECTOR Veronica Vazquez	
MAILING ADDRESS PO BOX490, UPLAND CA 91785			IDENTIFIER: Spa	
TIME IN 8:56 AM			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME OUT 9:05 AM			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
FACILITY ID FA0004653			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	
RELATED ID PR0015255			PE 3623	

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	7

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Spa is hereby open. Removed closure sign.
	Not In Compliance	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Observed fence covered with four sheets of signs bolted in and covering the vertical fence rails that are brittle. This is a temporary solution until fence is repaired/replaced permanently. Will reinspect by second routine inspection.
	Not In Compliance	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

Call Veronica Vazquez at (800) 442-2283 with questions.

Signature(s) of Acknowledgement

NAME:
TITLE:
Total # of Images: 0