



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dehs

(800) 442-2283

FACILITY NAME VALENCIA LEA MHP				DATE 4/11/2013	SIGNATURE
LOCATION 3850 E ATLANTIC AV, HIGHLAND, CA 92346				REINSPECTION DATE 10/11/2013	PERMIT EXPIRATION 6/30/2013
MAILING ADDRESS 3850 E ATLANTIC AV 39, HIGHLAND CA 92346				REHS Dior Porter	
FA # FA0008812	PR # PR0014233	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: spa
TIME IN 3:09 PM	TIME OUT 3:30 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine
					RESULT: 03 - Corrective Action / No Follow up Required
					ACTION: 01 - No Further Action Required




RECREATIONAL HEALTH - PUBLIC POOL/SPA

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50

Recreational Health Details

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	44
volume (gal)	1,320
area (sq ft)	80
occupancy	8

Inspection Violations

Critical Violations

1. Enclosure - Fence Height

Compliance Date not Specified

Not In Compliance

Violation Reference: CCR 24 - 3118B(a)1

Violation Description: The pool shall be enclosed by one or a combination of one of the following: a fence, portion of a building, wall or other approved durable enclosure. Doors, openable windows, or gates of living quarters or associated private premises shall not be permitted as part of the pool enclosure. The enclosure, doors and gates shall meet all of the following specifications:

1. The enclosure shall have a minimum effective perpendicular height of 5 meet as measured from the outside. For details see Title 24, section 3118B, Figures 31B-4 and 31B-5.

Inspector Comments: Observed portions of the fence and gates less than 4ft in height (43"-44"). All enclosures shall be a minimum of 4ft in height.

Overall Inspection Comments

unable to access pump room. Called 909-864-1200, no answer. Please provide keys addressed to Dior Porter.
Mailing address: 385 N. Arrowhead Ave 2nd floor, San Bernardino CA 92415