



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dehs

FACILITY NAME LA FITNESS				DATE 5/2/2013	SIGNATURE	
LOCATION 14485 PIPELINE AV, CHINO HILLS, CA 91709				REINSPECTION DATE 11/02/2013	PERMIT EXPIRATION 9/30/2013	
MAILING ADDRESS PO BOX 52110, IRVINE CA 92619				REHS Tin Nguyen		
FA # FA0000838	PR # PR0015846	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Spa	
TIME IN 9:35 AM	TIME OUT 9:50 AM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine	
					RESULT: 03 - Corrective Action / No Follow up Required	
					ACTION: 01 - No Further Action Required	

RECREATIONAL HEALTH - PUBLIC POOL/SPA




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

98

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	104.0
observed flow (gpm)	No Data
required flow (gpm)	61
volume (gal)	1,822
area (sq ft)	100
occupancy	10

36K448 Equipment - Flow Meter

POINTS
2

Compliance Date: Not Specified
Not In Compliance
Violation Reference - CCR - 3125B

Inspector Comments:
-Observed flow meter stuck for spa. Repair/replace flow meter for proper reading.

(Required flow rate: 61gpm)

Violation Description: A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow.

Overall Inspection Comments

pH: 7.4
Chlorine: 2.5 ppm
CYA: 0 ppm
Flow rate: stuck
Required flow rate: 61 gpm

Photo Attachments:
No Photo Attachments