



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dehs

FACILITY NAME IRONWOOD / FAIRWAY				DATE 5/6/2013	SIGNATURE
LOCATION 11100 4TH ST, RANCHO CUCAMONGA, CA 91730				REINSPECTION DATE 11/06/2013	PERMIT EXPIRATION 12/31/2013
MAILING ADDRESS 8 EXECUTIVE CR, IRVINE CA 92614				REHS Sumedha Singh	
FA # FA0012895	PR # PR0035018	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Fairway Spa
TIME IN 3:41 PM	TIME OUT 4:06 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine
				RESULT: 03 - Corrective Action / No Follow up Required	ACTION: 01 - No Further Action Required

RECREATIONAL HEALTH - PUBLIC POOL/SPA


Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

96

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K444 Equipment - Recirculation Pump/Filter/Separation Tank

POINTS
2

Compliance Date: **Not Specified**
Not In Compliance
Violation Reference - **HSC - 3120B, 3132B, 3141B**

Inspector Comments: Observed little to no variations in records in pump room. (ie, chlorine was always 5.0). Maintain actual daily records.

Violation Description: Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The pumps, filters and all related parts of the pool water purification system shall be kept in operation whenever the pool is available for use. All parts of the pool and related pool facilities and equipment shall be maintained in good repair.

The backwash from a diatomaceous earth filter shall discharge into a separation tank. The wastewater from the separation tank shall discharge into a sanitary sewer or other disposal system acceptable to the local wastewater agency.

The direction of flow for the recirculation equipment shall be labeled clearly with directional symbols such as arrows on all piping in the equipment area.

36K458 Maintenance - Test Kit/Daily Records

POINTS
2

Compliance Date: **Not Specified**
Not In Compliance
Violation Reference - **CCR - 65523, 65529**

Inspector Comments: Observed direction of water flow not labeled in pump room. Maintain proper labeling of direction of flow with directional symbols.

Observed leak from pump for spa jets. Repair and maintain as needed.

Violation Description: Appropriate test kits for measuring the pH, concentration of the disinfectant, and, when used, concentration of cyanuric acid shall be provided at each pool. The test kit shall be capable of testing for free chlorine residual.

The operator of each pool open for use shall keep a daily record of information regarding operation, including readings of disinfectant residual, pH and maintenance procedures such as cleaning of filters and quantity of chemicals used.

Overall Inspection Comments



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dehs

(800) 442-2283

FACILITY NAME IRONWOOD / FAIRWAY	DATE 5/6/2013	SIGNATURE 
LOCATION 11100 4TH ST, RANCHO CUCAMONGA, CA 91730		REHS Sumedha Singh

Signs that need to be posted:

REQUIRED SIGNS FOR POOLS

All signs must be posted in a location visible to all pool users.

1. "WARNING - NO LIFEGUARD ON DUTY"

- Required at all spas where lifeguard service is not provided.
- Letters must be at least 4" high.
- Sign must be located in plain view of persons entering the spa area.
- The sign also shall state in letters at least 1 inch (25 mm) high, "Children under the age of 14 shall not use pool without a parent or adult guardian in attendance."

2. ARTIFICIAL RESPIRATION AND CPR

- Sign must have illustrated diagrams with artificial respiration and CPR procedures.
- Text at least ¼ inch high
- Sign must be posted within the spa enclosure and be clearly visible.

3. EMERGENCY TELEPHONE NUMBERS

- Shall have "911" number.
- Shall include the number of the nearest emergency services.
- Shall include the name and street address of the pool facility shall be posted.
- Letters shall be not less than 4 inches (102 mm) high.

4. OCCUPANCY LOAD

- Must have clearly legible letter/numerals not less than 4 inches (102 mm) high.
- Shall indicate the maximum number of pool users permitted for each pool.
- The pool user capacity for all pools (except spas) shall be based on one pool user for every 20 square feet (1.858 m2) of pool water surface area.

5. "NO DIVING"

- Signs shall be posted in conspicuous places and shall state, "NO DIVING" at pools with a maximum water depth of 6 feet or less.
- Letters shall be not less than 4 inches (102 mm) high.

6. "NO USE OF POOL ALLOWED AFTER DARK"

- Where pools were constructed for which lighting was not required, a sign shall be posted at each pool entrance on the outside of the gate(s).
- Letters shall be not less than 4 inches (102 mm) high.

7. "KEEP CLOSED"

- A sign shall be posted on the exterior side of gates and doors leading into the pool enclosure area.
- Letters shall be not less than 4 inches (102 mm) high.

8. "Diarrhea"

- A sign in a language or diagram that states that persons having currently active diarrhea or who have had active diarrhea within the previous 14 days shall not be allowed to enter the pool water.
- Letters shall be at least 1 inch (25 mm) high.
- It shall be posted in a location visible to entrance area.

Photo Attachments:

No Photo Attachments