



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dehs

(800) 442-2283

FACILITY NAME VILLAGE ON THE GREEN APARTMENTS					DATE 5/7/2013	SIGNATURE	
LOCATION 9400 FAIRWAY VIEW PL, RANCHO CUCAMONGA, CA 91730					REINSPECTION DATE 11/07/2013	PERMIT EXPIRATION 7/31/2013	
MAILING ADDRESS 9400 FAIRWAY VIEW PL, RANCHO CUCAMONGA CA 91730					REHS Sumedha Singh		
FA # FA0014399	PR # PR0019027	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Pool		
TIME IN 4:26 PM	TIME OUT 5:00 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

RECREATIONAL HEALTH - PUBLIC POOL/SPA



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

96

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	70
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K430 Safety - Equipment/First Aid Kit

POINTS 2	Compliance Date: Not Specified
	Not In Compliance
	Violation Reference - CCR - 65539

Inspector Comments: Observed rope not attached to life ring. Maintain rope always attached to life ring in case of emergencies.

Violation Description: Every swimming pool shall be equipped for safety and rescue purposes with one or more rescue poles not less than 12 feet in length with body hooks, and one or more life rings having a minimum exterior diameter of 17 inches readily accessible for use. Such life rings shall have attached to them an 3/16 inch line long enough to span the maximum width of the pool. A first aid kit shall be provided at all swimming pools when required by DEHS.

36K460 Skimmers - Requirements

POINTS 2	Compliance Date: Not Specified
	Not In Compliance
	Violation Reference - CCR - 65533, 3136B

Inspector Comments: Observed weir gate missing inside skimmer.

Violation Description: Skimmers and water levels shall be maintained and operated to remove floating scum, sputum or debris continuously. The skimmer shall be recessed into the pool wall, individually adjustable for the rate of flow with either an external or internal device, provided with an air lock protective device and provided with a removable and cleanable screen or basket to trap objects.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:

No Photo Attachments