



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dehs

FACILITY NAME SYCAMORE PARK APARTMENTS				DATE 5/9/2013	SIGNATURE
LOCATION 1221 N VINEYARD , ONTARIO, CA 91764				REINSPECTION DATE 11/09/2013	PERMIT EXPIRATION 7/31/2013
MAILING ADDRESS 1156 N MOUNTAIN AV, UPLAND CA 91786				REHS Anies Kondoker	
FA # FA0008579	PR # PR0014434	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Pool
TIME IN 12:39 PM	TIME OUT 1:09 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine
				RESULT: 03 - Corrective Action / No Follow up Required	
				ACTION: 01 - No Further Action Required	

RECREATIONAL HEALTH - PUBLIC POOL/SPA



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

96

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	74
volume (gal)	26,500
area (sq ft)	800
occupancy	40

36K460 Skimmers - Requirements

POINTS 2	Compliance Date: Not Specified	Inspector Comments: - Provide weir gates to all skimmers. - Observed float assemblies on top of skimmer baskets. Place the float assemblies under the baskets.
	Not In Compliance	
	Violation Reference - CCR - 65533, 3136B	

Violation Description: Skimmers and water levels shall be maintained and operated to remove floating scum, sputum or debris continuously. The skimmer shall be recessed into the pool wall, individually adjustable for the rate of flow with either an external or internal device, provided with an air lock protective device and provided with a removable and cleanable screen or basket to trap objects.

36K472 Access - Steps - Handrails - Diving Area

POINTS 2	Compliance Date: Not Specified	Inspector Comments: Repair loose hand rail at deep end.
	Not In Compliance	
	Violation Reference - CCR - 3111B, 3113B	

Violation Description: Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.

Overall Inspection Comments

pH = 7.6
Free chlorine = 4 ppm
Cyanuric acid = 40 ppm
Flow rate = 80 gpm

Photo Attachments:
No Photo Attachments