



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dehs

FACILITY NAME ALOFT ONTARIO-RC				DATE 5/13/2013	SIGNATURE
LOCATION 10480 FOURTH ST, RANCHO CUCAMONGA, CA 91730				REINSPECTION DATE 11/13/2013	PERMIT EXPIRATION 1/31/2014
MAILING ADDRESS 10480 FOURTH ST, RANCHO CUCAMONGA CA 91730				REHS Sumedha Singh	
FA # FA0016266	PR # PR0021661	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Pool
TIME IN 10:43 AM	TIME OUT 11:34 AM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine
					RESULT: 03 - Corrective Action / No Follow up Required
					ACTION: 01 - No Further Action Required

RECREATIONAL HEALTH - PUBLIC POOL/SPA


Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

94

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	67
volume (gal)	24,160
area (sq ft)	760
occupancy	35

36K438 Enclosure - Critical - Gates Drowning Hazard

⚠ CRITICAL ⚠

POINTS
4

Compliance Date: Not Specified
Complied on 5/13/2013
Violation Reference - HSC - 3119B

Inspector Comments: Observed west gate not self-closing or self-latching. Corrected during inspection.

Violation Description: Gates and doors shall be equipped with self-closing and self-latching devices. The self-latching device shall keep the gate or door securely closed. Gates and doors shall open outwardly away from the pool except where otherwise prohibited by law. Gates and doors shall be capable of being locked during times when the pool is closed. The pool enclosure shall have at least one means of egress without a key for emergency purposes.

36K444 Equipment - Recirculation Pump/Filter/Separation Tank

POINTS
2

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC - 3120B, 3132B, 3141B

Inspector Comments: Observed flow meter stuck in equipment room. Adjust to flow at a minimum of 67 gpm.

Violation Description: Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The pumps, filters and all related parts of the pool water purification system shall be kept in operation whenever the pool is available for use. All parts of the pool and related pool facilities and equipment shall be maintained in good repair.

The backwash from a diatomaceous earth filter shall discharge into a separation tank. The wastewater from the separation tank shall discharge into a sanitary sewer or other disposal system acceptable to the local wastewater agency.

The direction of flow for the recirculation equipment shall be labeled clearly with directional symbols such as arrows on all piping in the equipment area.


Overall Inspection Comments



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dehs

(800) 442-2283

FACILITY NAME ALOFT ONTARIO-RC	DATE 5/13/2013	SIGNATURE 
LOCATION 10480 FOURTH ST, RANCHO CUCAMONGA, CA 91730	REHS Sumedha Singh	

REQUIRED SIGNS FOR POOLS

All signs must be posted in a location visible to all pool users.

1. "WARNING - NO LIFEGUARD ON DUTY"

- Required at all spas where lifeguard service is not provided.
- Letters must be at least 4" high.
- Sign must be located in plain view of persons entering the spa area.
- The sign also shall state in letters at least 1 inch (25 mm) high, "Children under the age of 14 shall not use pool without a parent or adult guardian in attendance."

2. ARTIFICIAL RESPIRATION AND CPR

- Sign must have illustrated diagrams with artificial respiration and CPR procedures.
- Text at least ¼ inch high
- Sign must be posted within the spa enclosure and be clearly visible.

3. EMERGENCY TELEPHONE NUMBERS

- Shall have "911" number.
- Shall include the number of the nearest emergency services.
- Shall include the name and street address of the pool facility shall be posted.
- Letters shall be not less than 4 inches (102 mm) high.

4. OCCUPANCY LOAD

- Must have clearly legible letter/numerals not less than 4 inches (102 mm) high.
- Shall indicate the maximum number of pool users permitted for each pool.
- The pool user capacity for all pools (except spas) shall be based on one pool user for every 20 square feet (1.858 m2) of pool water surface area.

5. "NO DIVING"

- Signs shall be posted in conspicuous places and shall state, "NO DIVING" at pools with a maximum water depth of 6 feet or less.
- Letters shall be not less than 4 inches (102 mm) high.

6. "NO USE OF POOL ALLOWED AFTER DARK"

- Where pools were constructed for which lighting was not required, a sign shall be posted at each pool entrance on the outside of the gate(s).
- Letters shall be not less than 4 inches (102 mm) high.

7. "KEEP CLOSED"

- A sign shall be posted on the exterior side of gates and doors leading into the pool enclosure area.
- Letters shall be not less than 4 inches (102 mm) high.

8. "Diarrhea"

- A sign in a language or diagram that states that persons having currently active diarrhea or who have had active diarrhea within the previous 14 days shall not be allowed to enter the pool water.
- Letters shall be at least 1 inch (25 mm) high.
- It shall be posted in a location visible to entrance area.

- Ensure all pump equipment has the directional flow of water.

Photo Attachments:

No Photo Attachments