



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dehs

FACILITY NAME VILLA GABRIEL HOA				DATE 5/14/2013	SIGNATURE
LOCATION 8300 GABRIEL DR, RANCHO CUCAMONGA, CA 91730				REINSPECTION DATE 11/14/2013	PERMIT EXPIRATION 10/31/2013
MAILING ADDRESS PO BOX 5022, UPLAND CA 91785				REHS Anies Kondoker	
FA # FA0004427	PR # PR0015418	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: pool
TIME IN 12:50 PM	TIME OUT 1:20 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine
					RESULT: 03 - Corrective Action / No Follow up Required
					ACTION: 01 - No Further Action Required

RECREATIONAL HEALTH - PUBLIC POOL/SPA


Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

96

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	80
volume (gal)	29,000
area (sq ft)	940
occupancy	42

36K448 Equipment - Flow Meter

POINTS
2

Compliance Date: Not Specified
Not In Compliance
Violation Reference - CCR - 3125B

Inspector Comments: Repair/replace non-functioning flow meter.

Violation Description: A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow.

36K466 Structure - Pool Shell

POINTS
2

Compliance Date: Not Specified
Not In Compliance
Violation Reference - CCR - 3108B

Inspector Comments: Repair chipped pool bottom.

Violation Description: The finished pool shell shall be lined with a smooth waterproof interior finish that will withstand repeated brushing, scrubbing, and cleaning procedures. The finish color shall be white. Tiles installed at the waterline shall be of contrasting color. A spa pool may be finished in a light color other than white when approved by the enforcing agent.

Overall Inspection Comments

pH = 8
Free chlorine = 7 ppm

This facility shall provide all required signs as written on a flyer sent by email.

Photo Attachments:

No Photo Attachments