



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

(800) 442-2283

www.sbcounty.gov/dehs

FACILITY NAME RANCHO MONTE VISTA MOBILEHOME PARK				DATE 5/23/2013	SIGNATURE
LOCATION 15050 MONTE VISTA AV, CHINO HILLS, CA 91710				REINSPECTION DATE 11/23/2013	PERMIT EXPIRATION 6/30/2013
MAILING ADDRESS 1801 E EDINGER AV STE 230, SANTA ANA CA 92705				REHS Tin Nguyen	
FA # FA0006998	PR # PR0014036	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Pool
TIME IN 3:36 PM	TIME OUT 4:04 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine
					RESULT: 03 - Corrective Action / No Follow up Required
					ACTION: 01 - No Further Action Required

RECREATIONAL HEALTH - PUBLIC POOL/SPA




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

94

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	197
volume (gal)	70,860
area (sq ft)	1,552
occupancy	76

36K448 Equipment - Flow Meter

POINTS
2

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 3125B

Inspector Comments:
 -Observed stuck flow meter. Repair/replace.

NOTE:
 -Maintain flow rate at 197 gallons per minute.

Violation Description: A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow. Flowmeter shall be maintained in good repair, accurately displaying flowrate.

36K460 Skimmers - Requirements

POINTS
2

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 65533, 3136B

Inspector Comments: Observed check valve missing in skimmer at 3.5 feet, 6 feet, and 9 feet. Repair/replace.

Violation Description: The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 75 percent of the required flow rate. Skimmers and water levels shall be maintained and operated to remove floating scum, sputum or debris continuously. The skimmer shall be recessed into the pool wall, individually adjustable for the rate of flow with either an external or internal device, provided with an air lock protective device and provided with a removable and cleanable screen or basket to trap objects.

36K472 Access - Steps - Handrails - Diving Area

POINTS
2

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 3111B, 3113B

Inspector Comments: Observed loose handrail at shallow end of pool. Tighten handrail at shallow end of pool.

Violation Description: Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.

Overall Inspection Comments



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dehs

(800) 442-2283

FACILITY NAME RANCHO MONTE VISTA MOBILEHOME PARK	DATE 5/23/2013	SIGNATURE
LOCATION 15050 MONTE VISTA AV, CHINO HILLS, CA 91710		REHS Tin Nguyen

pH: 7.4
Chlorine: 3.0 ppm
CYA: 65 ppm
Flow rate: n/a

Capacity: 70,860 gallons
Flow rate: 197
Surface area: 1,552 square feet
Occupancy: 76

Photo Attachments:
No Photo Attachments