



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

[www.sbcounty.gov/dehs](http://www.sbcounty.gov/dehs)

FACILITY NAME <b>INN AT SILVER LAKES</b>				DATE 5/29/2013	SIGNATURE <i>John Ramos</i>
LOCATION 14818 CLUBHOUSE DR, HELENDALE, CA 92342				REINSPECTION DATE 11/29/2013	PERMIT EXPIRATION 12/31/2013
MAILING ADDRESS PO BOX 299, HELENDALE CA 92342				REHS <b>John Ramos</b>	
FA # FA0007283	PR # PR0015590	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Small Pool
TIME IN 3:26 PM	TIME OUT 3:47 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine
					RESULT: 03 - Corrective Action / No Follow up Required
					ACTION: 01 - No Further Action Required

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**98**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	47
volume (gal)	16,830
area (sq ft)	528
occupancy	26

**36K448 Equipment - Flow Meter**

**POINTS**  
**2**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - CCR - 3125B

Inspector Comments: Observed stuck flow meter.  
 Repair.

**Violation Description:** A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow. Flowmeter shall be maintained in good repair, accurately displaying flowrate.

**Overall Inspection Comments**

Correct the above noted violation.

If you have any questions contact John Ramos at (800) 442-2283.  
 Our office has moved to 15900 Smoke Tree Street, Hesperia, CA 92345.

**Photo Attachments:**  
 No Photo Attachments