



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT


www.sbcounty.gov/dehs

(800) 442-2283

| | | | | | |
|---|----------------------------|--------------------------------|------------------------------|--|--|
| FACILITY NAME MEADOWOOD VILLAGE | | | | DATE 5/31/2013 | SIGNATURE |
| LOCATION 10153 SHADY OAKS DR, RANCHO CUCAMONGA, CA 91730 | | | | REINSPECTION DATE 10/31/2013 | PERMIT EXPIRATION 9/30/2013 |
| MAILING ADDRESS 1235 E FRANCIS ST STE E, ONTARIO CA 91761 | | | | REHS Sumedha Singh | |
| FA # FA0006124 | PR # PR0016916 | SR # Not Specified | CO # Not Specified | PE 3601 | PROGRAM IDENTIFIER: Spa |
| TIME IN 2:56 PM | TIME OUT 3:30 PM | CONTACT Not Captured | | | SERVICE: 003 - Inspection - Follow Up Inspection |
| | | | | | RESULT: 03 - Corrective Action / No Follow up Required |
| | | | | | ACTION: 15 - Permit Reinstated / Facility Re-opened |

RECREATIONAL HEALTH - PUBLIC POOL/SPA

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|---------|
| temperature (F) | No Data |
| observed flow (gpm) | No Data |
| required flow (gpm) | 60 |
| volume (gal) | 1,798 |
| area (sq ft) | 80 |
| occupancy | 8 |

36K992 Permit Reinstatement

| | | |
|---------------------|--------------------------------|---|
| POINTS NA | Compliance Date: Not Specified | Inspector Comments: Pool maintenance was able to drain spa and transfer pool water into spa. Chlorine level observed at 5.0 ppm. |
| | Not In Compliance | |
| | Violation Reference - HSC | |

Violation Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

| | | |
|---------------------|--------------------------------|---|
| POINTS NA | Compliance Date: Not Specified | Inspector Comments: Pool maintenance was able to drain spa and transfer pool water into spa. Chlorine level observed at 5.0 ppm. |
| | Not In Compliance | |
| | Violation Reference - HSC | |

Violation Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:
No Photo Attachments