



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**


(800) 442-2283

[www.sbcounty.gov/dehs](http://www.sbcounty.gov/dehs)

FACILITY NAME <b>PATIO APARTMENTS</b>				DATE <b>6/7/2013</b>	SIGNATURE
LOCATION <b>4811 CANOGA ST, MONTCLAIR, CA 91763</b>				REINSPECTION DATE <b>11/07/2013</b>	PERMIT EXPIRATION <b>6/30/2013</b>
MAILING ADDRESS <b>5111 BENITO, MONTCLAIR CA 91763</b>				REHS <b>Jose Rodriguez</b>	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT					
FA # <b>FA0008462</b>	PR # <b>PR0014526</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: Pool - Manager in Apt #J
TIME IN <b>3:54 PM</b>	TIME OUT <b>4:30 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: 003 - Inspection - Follow Up Inspection
					RESULT: 03 - Corrective Action / No Follow up Required
					ACTION: 15 - Permit Reinstated / Facility Re-opened

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	61
volume (gal)	21,870
area (sq ft)	648
occupancy	34

**36K992 Permit Reinstatement**

POINTS <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Pool is ok to re-open. Permit has been re-instated.
	Not In Compliance	
	Violation Reference - HSC	

**Violation Description:** The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

POINTS <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Re-inspection performed at this facility regarding chlorine levels and determine compliance.  Upon inspection, observed chlorine levels at 10 ppm.  Continue working on other violations cited on previous inspection report dated 06-06-13.
	Not In Compliance	
	Violation Reference - HSC	

**Violation Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**

No Photo Attachments