



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**




(800) 442-2283

[www.sbcounty.gov/dehs](http://www.sbcounty.gov/dehs)

FACILITY NAME <b>PARADISE TRAILER GROVE</b>					DATE <b>6/14/2013</b>	SIGNATURE	
LOCATION <b>5034 E HOLT BL, MONTCLAIR, CA 91763</b>					REINSPECTION DATE <b>11/14/2013</b>	PERMIT EXPIRATION <b>6/30/2013</b>	
MAILING ADDRESS <b>5034 E HOLT BL, MONTCLAIR, CA 91763</b>					<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT REHS <b>Jose Rodriguez</b>		
FA # <b>FA0007005</b>	PR # <b>PR0014031</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: Pool		
TIME IN <b>1:58 PM</b>	TIME OUT <b>2:18 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: 003 - Inspection - Follow Up Inspection		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	34
volume (gal)	12,285
area (sq ft)	364
occupancy	18

**36K994 Reinspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

**Inspector Comments:** Re-inspection performed at this facility to determine compliance with installation of separation tank.  
 -Upon inspection, observed separation tank installed, however, it was installed as a closed loop system. Separation tank shall drain to a sewer line or other method as long as it does not create a nuisance for the residents.  
 -Additionally, the sight glass is missing. Provide a sight glass on pipe that goes from filter to separation tank.  
 -Have work done by July.

**Violation Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**  
 No Photo Attachments