



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dehs

FACILITY NAME RANCHO VILLA					DATE 6/24/2013	SIGNATURE	
LOCATION 8033 RAMONA , RANCHO CUCAMONGA, CA 91730					REINSPECTION DATE 12/24/2013	PERMIT EXPIRATION 5/31/2014	
MAILING ADDRESS 8033 RAMONA , RANCHO CUCAMONGA, CA 91730					REHS Isaac Gebreslassie		
FA # FA0005705	PR # PR0014982	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Pool		
TIME IN 11:51 AM	TIME OUT 12:17 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

RECREATIONAL HEALTH - PUBLIC POOL/SPA



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

94

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	50
required flow (gpm)	55
volume (gal)	33,000
area (sq ft)	800
occupancy	40

36K454 Maintenance - Cleanliness

POINTS	Compliance Date: Not Specified
2	Not In Compliance
	Violation Reference - CCR - 65533

Inspector Comments: Observed algae like green stain on sides of pool shell. Clean and maintain.

Violation Description: Floating scum, sputum or debris shall not be allowed to accumulate in the pool. The bottom and sides of the pool shall be cleaned as often as necessary to be kept in a clean condition. The sides and bottom of pools, decks and other surfaces shall be kept free of slime and algae.

36K478 Disposal - Wastewater

POINTS	Compliance Date: Not Specified
2	Not In Compliance
	Violation Reference - CCR 24 - 3141B

Inspector Comments: Observed waste water from separation tank being discharged out on the ground. Ensure waste water is dispose of into sanitary sewer.

Violation Description: Material cleaned from filters and backwash water from any recirculation system shall be disposed in a manner that is acceptable to the local wastewater agency and will not create a nuisance.

36K482 Restrooms - Toilet Facilities - Showers - Drinking Fountain

POINTS	Compliance Date: Not Specified
2	Not In Compliance
	Violation Reference - CCR - 65535, 65551, 3117B

Inspector Comments: Observed shower knob dismantled to prevent vandalism. Keep shower in good repair. Also rest rooms locked and rendered inaccessible for the same reason. Keep rest rooms accessible to patrons.

Violation Description: Toilets, urinals, showers, wash basins and other plumbing fixtures shall be maintained in a clean condition, and in good repair. For shower, toilet and dressing facilities, the walls, partitions, doors, lockers and similar surfaces which require periodic cleaning shall be maintained smooth and finished so as to facilitate- cleaning. Showers shall be provided with soap in soap dispensers or containers. For toilet facilities, handwashing detergent or soap, sanitary towels or hot air blowers, and toilet tissues shall be provided in permanently installed dispensing devices. Showers and lavatories shall be provided with hot and cold water faucets.

One guarded jet drinking fountain shall be provided for the first 250 bathers and an additional fountain shall be provided for each additional 200 bathers or fraction thereof.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:

No Photo Attachments