



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

FACILITY NAME <b>SPLASH KINGDOM WATERPARK</b>					DATE <b>6/25/2013</b>	SIGNATURE 	
LOCATION <b>1101 N CALIFORNIA ST, REDLANDS, CA 92374</b>					REINSPECTION DATE <b>12/25/2013</b>	PERMIT EXPIRATION <b>10/31/2012</b>	
MAILING ADDRESS <b>1101 CALIFORNIA DR, REDLANDS CA 92374</b>					REHS <b>Marilyn Krichbaum</b>		
FA # <b>FA0001431</b>	PR # <b>PR0015705</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: Spa		
TIME IN <b>12:05 PM</b>	TIME OUT <b>12:45 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**


Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**100**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**36K952 Drained Pool or Spa Inspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

**Inspector Comments:** Spa is drained and not being used. Equipment is disconnected. Health permit is required until the spa is properly demolished and the proper permits obtained.

**Violation Description:** An inspection was conducted at this time on a drained pool or spa. Contact DEHS prior to filling with water and/or operating.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**

No Photo Attachments