



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME SOMERSET APARTMENTS					DATE 7/10/2013	SIGNATURE	
LOCATION 12180 RAMONA , CHINO, CA 91710					REINSPECTION DATE 1/10/2014	PERMIT EXPIRATION 8/31/2013	
MAILING ADDRESS 12180 RAMONA , CHINO, CA 91710					REHS Nick Thalasin		
FA # FA0005003	PR # PR0015170	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Back spa		
TIME IN 1:45 PM	TIME OUT 2:55 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

RECREATIONAL HEALTH - PUBLIC POOL/SPA


Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

96

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	102.0
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K404 Water Quality - Critical - High Disinfectant Level

⚠ CRITICAL ⚠

POINTS
4

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 65529

Inspector Comments: Observed the chlorine level is above 10 ppm; Free chlorine residual shall not exceed 10 ppm.
 Corrected during inspection.

Violation Description: Concentration of available disinfectant shall not exceed approved level. Free chlorine residual shall not exceed 10 ppm.

Overall Inspection Comments

Note: Please supply a Gate Opener and keys to facilitate inspection.

Back Spa

Photo Attachments:

No Photo Attachments