



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

FACILITY NAME <b>DOUBLETREE HOTEL ONTARIO</b>					DATE <b>7/16/2013</b>	SIGNATURE <i>Scott E. Case</i>	
LOCATION <b>222 N VINEYARD AV, ONTARIO, CA 91764</b>					REINSPECTION DATE <b>1/16/2014</b>	PERMIT EXPIRATION <b>6/30/2014</b>	
MAILING ADDRESS <b>222 N VINEYARD AV, ONTARIO, CA 91764</b>					REHS <b>Sierra Clayborn</b>		
<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT					PROGRAM IDENTIFIER: Spa		
FA # <b>FA0009788</b>	PR # <b>PR0015943</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	SERVICE: 001 - Inspection - Routine		
TIME IN <b>4:30 PM</b>	TIME OUT <b>4:57 PM</b>	CONTACT <b>Not Captured</b>			RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**98**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	101.8
observed flow (gpm)	60
required flow (gpm)	74
volume (gal)	2,223
area (sq ft)	112
occupancy	11

**36K460 Skimmers - Requirements**

**POINTS**  
**2**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - CCR - 65533, 3136B

**Inspector Comments:** Observed an excessive amount of debris in skimmer (sand, small leaf particles). Skimmer must be able to provide 75% of spa suction compared to main drain at 25% suction.

**Violation Description:** The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 75 percent of the required flow rate. Skimmers and water levels shall be maintained and operated to remove floating scum, sputum or debris continuously. The skimmer shall be recessed into the pool wall, individually adjustable for the rate of flow with either an external or internal device, provided with an air lock protective device and provided with a removable and cleanable screen or basket to trap objects.

**Overall Inspection Comments**

Observed new pool/spa signs on property.  
 Ensure that emergency contact information signage has the 4 inch lettering for 2014 pool season.

**Photo Attachments:**  
 No Photo Attachments