



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME <b>VILLA PARK APARTMENTS</b>					DATE <b>7/19/2013</b>	SIGNATURE	
LOCATION <b>1483 E LYNWOOD, SAN BERNARDINO, CA 92404</b>					REINSPECTION DATE <b>8/02/2013</b>	PERMIT EXPIRATION <b>12/31/2013</b>	
MAILING ADDRESS <b>1483 E LYNWOOD, SAN BERNARDINO, CA 92404</b>					REHS <b>Chaz Harrison</b>		
FA # <b>FA0008870</b>	PR # <b>PR0015959</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: Pool		
TIME IN <b>10:36 AM</b>	TIME OUT <b>10:54 AM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - Inspection - Routine		
					RESULT: 05 - Corrective Action / Follow up Required		
					ACTION: 14 - Permit Suspd / Facility Closed fencing iss		

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**96**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**36K436 Enclosure - Critical - Enclosure Drowning Hazard**

**⚠ CRITICAL ⚠**

<b>POINTS</b> <b>4</b>	Compliance Date: <b>Not Specified</b>	<b>Inspector Comments:</b> Observed apartment window leading into pool area opening greater than 4 inches. Ensure to install an opening prevention device that will prevent windows leading into the pool from opening greater than 4 inches.
	<b>Not In Compliance</b>	
	Violation Reference - CCR 24 - 3119B	

**Violation Description:** The pool shall be enclosed by one or a combination of the following: a fence; portion of a building; wall; or other approved durable enclosure. Doors, windows gates of living units or associated private premises shall not be permitted as part of the pool enclosure. The enclosure shall have a minimum effective perpendicular height of 5 feet. Openings, holes or gaps in the enclosure, doors and/or gates shall not allow the passage of a 4-inch diameter sphere. The enclosure shall be constructed over a hard and permanent material equivalent to concrete. The enclosure shall be designed and constructed so that it cannot be readily climbed by small children.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**

No Photo Attachments