



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**



(800) 442-2283

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

FACILITY NAME <b>RODEWAY INN</b>				DATE <b>7/22/2013</b>	SIGNATURE	
LOCATION <b>4075 E GUASTI RD, ONTARIO, CA 91761</b>				REINSPECTION DATE <b>12/22/2013</b>	PERMIT EXPIRATION <b>1/31/2014</b>	
MAILING ADDRESS <b>4075 E GUASTI RD, ONTARIO, CA 91761</b>				<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT REHS <b>Sierra Clayborn</b>		
FA # <b>FA0008435</b>	PR # <b>PR0014171</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: Pool	
TIME IN <b>9:47 AM</b>	TIME OUT <b>10:07 AM</b>	CONTACT <b>Not Captured</b>			SERVICE: 003 - Inspection - Follow Up Inspection	
					RESULT: 03 - Corrective Action / No Follow up Required	
					ACTION: 15 - Permit Reinstated / Facility Re-opened	

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**36K992 Permit Reinstatement**

POINTS  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

Inspector Comments:

Violation Description: The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

POINTS  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

Inspector Comments: During routine inspection, observed pool pump to be out of compliance with AB1020 regulations, in that the pump did not have an SVRS system in place and the main drain was not split.

Violation Description: Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

Observed SVRS Vac-Less system in place on both pool, spa and jet pumps.  
 Observed a new separation tank in place with proper plumbing to sewer opening.  
 Observed flow meter with sediment in tubing, inhibiting bobbin from free movement.  
 Observed chemicals in pool to be within acceptable ranges; chlorine at 3ppm and pH at 8.

Pool permit reinstated; pool area open for use.

**Photo Attachments:**

No Photo Attachments