



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

FACILITY NAME <b>SPLASH KINGDOM WATERPARK</b>					DATE <b>8/5/2013</b>	SIGNATURE	
LOCATION <b>1101 N CALIFORNIA ST, REDLANDS, CA 92374</b>					REINSPECTION DATE <b>2/05/2014</b>	PERMIT EXPIRATION <b>10/31/2013</b>	
MAILING ADDRESS <b>1101 CALIFORNIA DR, REDLANDS CA 92374</b>					REHS <b>Yong Aday</b>		
FA # <b>FA0001431</b>	PR # <b>PR0015705</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: Spa		
TIME IN <b>11:21 AM</b>	TIME OUT <b>11:25 AM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - Inspection - Routine		
					RESULT: 01 - Corrective Action Not Required		
					ACTION: 01 - No Further Action Required		

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**


Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**100**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**36K952 Drained Pool or Spa Inspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

Inspector Comments: The spa was drained and dry at this time.

**Violation Description:** An inspection was conducted at this time on a drained pool or spa. Contact DEHS prior to filling with water and/or operating.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**

No Photo Attachments