



**County of San Bernardino • Department of Public Health  
Division of Environmental Health Services  
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

**(800) 442-2283**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

FACILITY NAME <b>RANCH MEADOWS</b>					DATE <b>8/6/2013</b>	SIGNATURE	
LOCATION <b>28950 LOVE ST, HIGHLAND, CA 92346</b>					REINSPECTION DATE <b>2/06/2014</b>	PERMIT EXPIRATION <b>6/30/2014</b>	
MAILING ADDRESS <b>7136 CLUB VIEW DR, HIGHLAND CA 92346</b>					REHS <b>Dior Porter</b>		
FA # <b>FA0001432</b>	PR # <b>PR0015698</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: pool		
TIME IN <b>1:36 PM</b>	TIME OUT <b>2:15 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		




**RECREATIONAL HEALTH - PUBLIC POOL/SPA**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**96**  
SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	300
required flow (gpm)	236
volume (gal)	85,000
area (sq ft)	3,600
occupancy	180

**36K430 Safety - Equipment/First Aid Kit**

**POINTS**  
**2**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - CCR - 65539

**Inspector Comments:** Observed line of insufficient length on life ring. Provide a line long enough to span the maximum width of the pool.

**Violation Description:** Every swimming pool shall be equipped for safety and rescue purposes with one or more rescue poles not less than 12 feet in length with body hooks, and one or more life rings having a minimum exterior diameter of 17 inches readily accessible for use. Such life rings shall have attached to them an 3/16 inch line long enough to span the maximum width of the pool. A first aid kit shall be provided at all swimming pools when required by DEHS.

**36K474 Lighting - Adequate Lighting and Ventilation**

**POINTS**  
**2**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - SBCC - 3115B, 3106B, 3121B

**Inspector Comments:** Observed dim light near 5ft deep end. Replace bulb.

**Violation Description:** Pools used at night shall be equipped with underwater lighting fixtures that will provide complete illumination to all underwater areas of the pool with no blind spots. Pool deck areas and emergency egress areas shall be provided with lighting so that persons walking on the deck can identify hazards. Lighting fixtures shall be aimed towards the deck area and away from the pool surface insofar as practical. Artificial lighting shall be provided at all spray ground pads which are used at night or which do not have adequate natural lighting so that all portions of the spray pad and deck may be seen easily.

Indoor pools, dressing rooms and toilet rooms shall be ventilated according to the requirements in Chapter 4 of the California Mechanical Code.

**Overall Inspection Comments**

Note: unable to survey entire fence area due to bushes. Ensure all parts of the enclosure are in good repair.

**Photo Attachments:**

No Photo Attachments