



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME MOTEL 6 4731					DATE 8/6/2013	SIGNATURE	
LOCATION 1560 E 4TH ST, ONTARIO, CA 91764					REINSPECTION DATE 2/06/2014	PERMIT EXPIRATION 4/30/2014	
MAILING ADDRESS 1260 UNIVERSITY AV, RIVERSIDE CA 92507					REHS Anies Kondoker		
FA # FA0008580	PR # PR0015174	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: pool		
TIME IN 2:27 PM	TIME OUT 3:04 PM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		




RECREATIONAL HEALTH - PUBLIC POOL/SPA

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

92
SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	40
volume (gal)	16,500
area (sq ft)	545
occupancy	27

36K448 Equipment - Flow Meter

POINTS	Compliance Date: Not Specified
2	Not In Compliance
	Violation Reference - CCR - 3125B

Inspector Comments: Repair/replace non-functioning flow meter. Ensure to achieve flow rate at about 40 gpm.

Violation Description: A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow. Flowmeter shall be maintained in good repair, accurately displaying flowrate.

36K454 Maintenance - Cleanliness

POINTS	Compliance Date: Not Specified
2	Not In Compliance
	Violation Reference - CCR - 65533

Inspector Comments: Observed debris accumulation on pool bottom. Maintain clean.

Violation Description: Floating scum, sputum or debris shall not be allowed to accumulate in the pool. The bottom and sides of the pool shall be cleaned as often as necessary to be kept in a clean condition. The sides and bottom of pools, decks and other surfaces shall be kept free of slime and algae.

36K472 Access - Steps - Handrails - Diving Area

POINTS	Compliance Date: Not Specified
2	Not In Compliance
	Violation Reference - CCR - 3111B, 3113B

Inspector Comments: Fasten loose handrail at deep end.

Violation Description: Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.

36K474 Lighting - Adequate Lighting and Ventilation

POINTS	Compliance Date: Not Specified
2	Not In Compliance
	Violation Reference - SBCC - 3115B, 3106B, 3121B

Inspector Comments: Repair/replace non-functioning pool light.

Violation Description: Pools used at night shall be equipped with underwater lighting fixtures that will provide complete illumination to all underwater areas of the pool with no blind spots. Pool deck areas and emergency egress areas shall be provided with lighting so that persons walking on the deck can identify hazards. Lighting fixtures shall be aimed towards the deck area and away from the pool surface insofar as practical. Artificial lighting shall be provided at all spray ground pads which are used at night or which do not have adequate natural lighting so that all portions of the spray pad and deck may be seen easily.

Indoor pools, dressing rooms and toilet rooms shall be ventilated according to the requirements in Chapter 4 of the California Mechanical Code.

Overall Inspection Comments

No summary comments have been made for this inspection.



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME MOTEL 6 4731	DATE 8/6/2013	SIGNATURE
LOCATION 1560 E 4TH ST, ONTARIO, CA 91764		REHS Anies Kondoker

Photo Attachments:

No Photo Attachments