



**County of San Bernardino • Department of Public Health  
Division of Environmental Health Services  
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

**(800) 442-2283**

|  |                            |                                |                              |                                       |   |  |
|--|----------------------------|--------------------------------|------------------------------|---------------------------------------|---|--|
| FACILITY NAME<br><b>MOTEL 6 4731</b>                             |                            |                                |                              | DATE<br><b>5/20/2014</b>              | SIGNATURE   |  |
| LOCATION<br><b>1560 E 4TH ST, ONTARIO, CA 91764</b>              |                            |                                |                              | REINSPECTION DATE<br><b>6/03/2014</b> | PERMIT EXPIRATION<br><b>4/30/2014</b>               |  |
| MAILING ADDRESS<br><b>1260 UNIVERSITY AV, RIVERSIDE CA 92507</b> |                            |                                |                              | REHS<br><b>Anies Kondoker</b>         |   |  |
| FA #<br><b>FA0008580</b>   | PR #<br><b>PR0015174</b>   | SR #<br><b>Not Specified</b>   | CO #<br><b>Not Specified</b> | PE<br><b>3601</b>                     | PROGRAM IDENTIFIER: pool                            |  |
| TIME IN<br><b>3:40 PM</b>  | TIME OUT<br><b>4:19 PM</b> | CONTACT<br><b>Not Captured</b> |                              |                                       | SERVICE: 001 - INSPECTION - ROUTINE                 |  |
|  |                            |                                |                              |                                       | RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQUIRED |  |
|  |                            |                                |                              |                                       | ACTION: 13 - PERMIT SUSPENDED / FACILITY CLOSED     |  |




**RECREATIONAL HEALTH - PUBLIC POOL**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

**80**

SCORE



|                     |         |
|---------------------|---------|
| temperature (F)     | No Data |
| observed flow (gpm) | No Data |
| required flow (gpm) | 40      |
| volume (gal)        | 16,500  |
| area (sq ft)        | 545     |
| occupancy           | 27      |

**36K995 Permit - Suspension**

**⚠ CRITICAL ⚠**

|                            |                                |   |
|----------------------------|--------------------------------|---|
| <b>POINTS</b><br><b>NA</b> | Compliance Date: Not Specified | <b>Inspector Comments:</b> Pool permit is suspended due to non-functioning recirculation system. Call 800-442-2283 for reopening. Ensure that pH and chlorine level are within legal limit. |
|                            | Not In Compliance              |   |
|                            | Violation Reference - HSC      |   |

**Violation Description:** Violation(s) observed pose an immediate threat to public health and safety. The health permit to operate is hereby suspended and the pool/spa ordered closed until the listed violation(s) have been corrected and verified by Environmental Health Services (EHS). The facility is to remain closed until permission from EHS is given. Contact your inspector at your local office to schedule a reinspection to reinstate the health permit. The facility is posted closed; do not move, hide, or remove the sign. Reopening of the pool/spa without the approval by EHS, may result in an hourly billable Professional Services fee.

**36K442 Equipment - Critical - Non-Functioning Recirculation System**

**⚠ CRITICAL ⚠**

|                           |                                   |  |
|---------------------------|-----------------------------------|--|
| <b>POINTS</b><br><b>4</b> | Compliance Date: Not Specified    | <b>Inspector Comments:</b> Observed non-functional recirculation system. Ensure that recirculation system is fully functional during open hours. |
|                           | Not In Compliance                 |  |
|                           | Violation Reference - CCR - 65525 |  |

**Violation Description:** Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The pumps, filters and all related parts of the pool water purification system shall be kept in operation whenever the pool is available for use.

**36K414 Water Quality - Non-Critical - pH High/Low**

|                           |                                   |   |
|---------------------------|-----------------------------------|---|
| <b>POINTS</b><br><b>2</b> | Compliance Date: Not Specified    | <b>Inspector Comments:</b> Measured pH at 7.0.. Maintain at 7.2 to 8.0. |
|                           | Not In Compliance                 |   |
|                           | Violation Reference - CCR - 65529 |   |

**Violation Description:** Water shall be maintained in an alkaline condition at a pH between 7.2 and 8.0.

**36K418 Water Quality - Cyanurates**

|                           |                                   |  |
|---------------------------|-----------------------------------|--|
| <b>POINTS</b><br><b>2</b> | Compliance Date: Not Specified    | <b>Inspector Comments:</b> Measured cyanuric acid above 100 ppm. Maintain at or below 100 ppm. |
|                           | Not In Compliance                 |  |
|                           | Violation Reference - CCR - 65529 |  |

**Violation Description:** The cyanuric acid concentration in any pool shall not exceeded 100 ppm.



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

**(800) 442-2283**

|   |                               |           |
|---|-------------------------------|-----------|
| FACILITY NAME<br><b>MOTEL 6 4731</b>                | DATE<br><b>5/20/2014</b>      | SIGNATURE |
| LOCATION<br><b>1560 E 4TH ST, ONTARIO, CA 91764</b> | REHS<br><b>Anies Kondoker</b> |           |

**36K444 Equipment - Recirculation Pump/Filter/Separation Tank**

|                           |   |  |
|---------------------------|---|--|
| <b>POINTS</b><br><b>2</b> | Compliance Date: Not Specified                  | <b>Inspector Comments:</b> Observed direction of flow for recirculation system not labeled.<br>Ensure to clearly label recirculation equipment with directional symbols. |
|                           | Not In Compliance                               |  |
|                           | Violation Reference - HSC - 3120B, 3132B, 3141B |  |

**Violation Description:** Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The pumps, filters and all related parts of the pool water purification system shall be kept in operation whenever the pool is available for use. All parts of the pool and related pool facilities and equipment shall be maintained in good repair.

The backwash from a diatomaceous earth filter shall discharge into a separation tank. The wastewater from the separation tank shall discharge into a sanitary sewer or other disposal system acceptable to the local wastewater agency.

The direction of flow for the recirculation equipment shall be labeled clearly with directional symbols such as arrows on all piping in the equipment area.

**36K454 Maintenance - Cleanliness**

|                           |                                   |   |
|---------------------------|-----------------------------------|---|
| <b>POINTS</b><br><b>2</b> | Compliance Date: Not Specified    | <b>Inspector Comments:</b> Observed accumulation of floating debris and debris on pool bottom.<br>Maintain clean. |
|                           | Not In Compliance                 |   |
|                           | Violation Reference - CCR - 65533 |   |

**Violation Description:** Floating scum, sputum or debris shall not be allowed to accumulate in the pool. The bottom and sides of the pool shall be cleaned as often as necessary to be kept in a clean condition. The sides and bottom of pools, decks and other surfaces shall be kept free of slime and algae.

**36K458 Maintenance - Test Kit/Daily Records**

|                           |  |   |
|---------------------------|--|---|
| <b>POINTS</b><br><b>2</b> | Compliance Date: Not Specified           | <b>Inspector Comments:</b> Observed missing current records of pool and spa chemical readings.<br>Ensure to maintain a current log. |
|                           | Not In Compliance                        |   |
|                           | Violation Reference - CCR - 65523, 65529 |   |

**Violation Description:** Appropriate test kits for measuring the pH, concentration of the disinfectant, and, when used, concentration of cyanuric acid shall be provided at each pool. The test kit shall be capable of testing for free chlorine residual.

The operator of each pool open for use shall keep a daily record of information regarding operation, including readings of disinfectant residual, pH and maintenance procedures such as cleaning of filters and quantity of chemicals used.

**36K460 Skimmers - Requirements**

|                           |  |  |
|---------------------------|--|--|
| <b>POINTS</b><br><b>2</b> | Compliance Date: Not Specified           | <b>Inspector Comments:</b> Observed missing check valve and float assembly in skimmer.<br>Replace. |
|                           | Not In Compliance                        |  |
|                           | Violation Reference - CCR - 65533, 3136B |  |

**Violation Description:** The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 75 percent of the required flow rate. Skimmers and water levels shall be maintained and operated to remove floating scum, sputum or debris continuously. The skimmer shall be recessed into the pool wall, individually adjustable for the rate of flow with either an external or internal device, provided with an air lock protective device and provided with a removable and cleanable screen or basket to trap objects.

**36K466 Structure - Pool Shell**

|                           |                                   |   |
|---------------------------|-----------------------------------|---|
| <b>POINTS</b><br><b>2</b> | Compliance Date: Not Specified    | <b>Inspector Comments:</b> Observed missing waterline tile near handrails at deep end.<br>Replace the tile. |
|                           | Not In Compliance                 |   |
|                           | Violation Reference - CCR - 3108B |   |

**Violation Description:** The finished pool shell shall be lined with a smooth waterproof interior finish that will withstand repeated brushing, scrubbing, and cleaning procedures. The finish color shall be white. Tiles installed at the waterline shall be of contrasting color. A spa pool may be finished in a light color other than white when approved by the enforcing agent. Pool shell shall be maintained in good repair.

**36K472 Access - Steps - Handrails - Diving Area**

|                           |  |  |
|---------------------------|--|--|
| <b>POINTS</b><br><b>2</b> | Compliance Date: Not Specified           | <b>Inspector Comments:</b> Observed 1 loose handrail at deep end.<br>Tighten loose handrail. |
|                           | Not In Compliance                        |  |
|                           | Violation Reference - CCR - 3111B, 3113B |  |

**Violation Description:** Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

**(800) 442-2283**

|  |                        |           |
|--|------------------------|-----------|
| FACILITY NAME<br>MOTEL 6 4731                | DATE<br>5/20/2014      | SIGNATURE |
| LOCATION<br>1560 E 4TH ST, ONTARIO, CA 91764 | REHS<br>Anies Kondoker |           |

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**

No Photo Attachments