



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**



(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME BEST WESTERN				DATE 5/23/2014	SIGNATURE	
LOCATION 3400 SHELBY ST, ONTARIO, CA 91764				REINSPECTION DATE Not Specified	PERMIT EXPIRATION 12/31/2014	
MAILING ADDRESS 3400 SHELBY ST, ONTARIO, CA 91764				REHS Anies Kondoker		
FA # FA0004209	PR # PR0015941	SR # Not Specified	CO # Not Specified	PE 3605	PROGRAM IDENTIFIER: Spa	
TIME IN 9:44 AM	TIME OUT 10:16 AM	CONTACT Not Captured			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
					RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP REQ	
					ACTION: 01 - NO FURTHER ACTION REQUIRED	

RECREATIONAL HEALTH - PUBLIC SPA

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	66
volume (gal)	1,987
area (sq ft)	113
occupancy	11

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: _____
	Not In Compliance	
	Violation Reference - HSC	

Violation Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

- Observed east gate self-closing and self-latching.
- Observed new safety signs posted in pool and spa enclosures.
Ensure to write down name and address of pool and spa facilities, and phone number of the nearest emergency service on safety signs.
- Place "Keep Closed" and diarrhea signs on pool and spa gates.
Observed this sign was posted on a wall of pool enclosure by pump room.
Obtain more of this sign to be placed on other gates.
- Inspector reviewed pool and spa violations with Cirilo, a maintenance person.
Correct all violations by July 1, 2014.

Photo Attachments:

No Photo Attachments