



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME RED ROOF INN					DATE 6/3/2014	SIGNATURE <i>Sandra Sosa</i>	
LOCATION 13409 MARIPOSA RD, VICTORVILLE, CA 92392					REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2014	
MAILING ADDRESS 106 CITRUS RANCH RD, SAN DIMAS CA 91773					REHS Veronica Vazquez		
FA # FA0004486	PR # PR0013928	SR # Not Specified	CO # Not Specified	PE 3605	PROGRAM IDENTIFIER: South Spa		
TIME IN 12:10 PM	TIME OUT 12:30 PM	CONTACT Not Captured			SERVICE: 001 - INSPECTION - ROUTINE		
					RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP REQ		
					ACTION: 01 - NO FURTHER ACTION REQUIRED		

RECREATIONAL HEALTH - Public Spa



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

96

SCORE

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	27
volume (gal)	800
area (sq ft)	50
occupancy	5

36K438 Enclosure - Critical - Gates Drowning Hazard



POINTS 4	Comply by: 6/3/2014	Inspector Comments: Immediately remove lock on pool gate latch to allow pool gate to fully close and latch. Observed lock blocking the pool gate from closing. Corrected on site. Operator removed lock from pool gate latch. Observed pool gate self-closing and latching.
	Complied on 6/3/2014	
	Violation Reference - HSC - 3119B	

Violation Description: Gates and doors shall be equipped with self-closing and self-latching devices. The self-latching device shall keep the gate or door securely closed. Gates and doors shall open outwardly away from the pool except where otherwise prohibited by law. Gates and doors shall be capable of being locked during times when the pool is closed. The pool enclosure shall have at least one means of egress without a key for emergency purposes.

36K952 Drained Pool or Spa Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Observed south spa closed off with caution tape. Ensure to keep spa free of water. Observed two inches of water in the south spa. Operator states water leaks from north spa.
	Not In Compliance	
	Violation Reference - HSC	

Violation Description: An inspection was conducted at this time on a drained pool or spa. Contact DEHS prior to filling with water and/or operating.

Overall Inspection Comments

Operator states south pool will be demolished. Please obtain demolition permit and submit to DEHS to inactivate health permit.

Call Veronica Vazquez with questions at (800) 442-2283.

Photo Attachments:

No Photo Attachments