



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME CAL STATE UNIVERSITY				DATE 6/5/2014	SIGNATURE	
LOCATION 5500 UNIVERSITY PKWY, SAN BERNARDINO, CA 92407				REINSPECTION DATE 6/19/2014	PERMIT EXPIRATION	
MAILING ADDRESS 5500 UNIVERSITY PKWY, SAN BERNARDINO CA 92407				REHS Breyanna Lyles		
FA # FA0006500	PR # PR0014826	SR # Not Specified	CO # Not Specified	PE 3603	PROGRAM IDENTIFIER: Coussoulis Old Pool	
TIME IN 11:40 AM	TIME OUT 11:52 AM	CONTACT Not Captured			SERVICE: 001 - INSPECTION - ROUTINE	
				RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQUIR		
				ACTION: 13 - PERMIT SUSPENDED / FACILITY CLOSED		

RECREATIONAL HEALTH - Public School Pool / Spa



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

100

SCORE

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	414
volume (gal)	240,000
area (sq ft)	No Data
occupancy	143

36K952 Drained Pool or Spa Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Observed a drained pool at time of inspection. Health Permit is suspended, and the pool/spa is posted closed at this time. The pool shall remain closed and secured until plans have been submitted to and approved by EHS for either demolition or filling again for operation.
	Not In Compliance	
	Violation Reference - HSC	

Violation Description: An inspection was conducted at this time on a drained pool or spa. Contact DEHS prior to filling with water and/or operating.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:

No Photo Attachments