



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

| | | | | | | | |
|---|----------------------------|--------------------------------|------------------------------|-------------------|---|--|--|
| FACILITY NAME IRONWOOD / FAIRWAY | | | | | DATE 6/13/2014 | SIGNATURE | |
| LOCATION 11100 4TH ST, RANCHO CUCAMONGA, CA 91730 | | | | | REINSPECTION DATE Not Specified | PERMIT EXPIRATION 12/31/2014 | |
| MAILING ADDRESS 8 EXECUTIVE CR, IRVINE CA 92614 | | | | | REHS Nick Thalasinios | | |
| FA # FA0012895 | PR # PR0035018 | SR # Not Specified | CO # Not Specified | PE 3623 | PROGRAM IDENTIFIER: Fairway Spa | | |
| TIME IN 2:00 PM | TIME OUT 2:35 PM | CONTACT Not Captured | | | SERVICE: 001 - INSPECTION - ROUTINE | | |
| | | | | | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP REQ | | |
| | | | | | ACTION: 01 - NO FURTHER ACTION REQUIRED | | |




RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

94

SCORE



| | |
|---------------------|---------|
| temperature (F) | 101.0 |
| observed flow (gpm) | No Data |
| required flow (gpm) | No Data |
| volume (gal) | No Data |
| area (sq ft) | No Data |
| occupancy | No Data |

36K427 Safety - Safety Signs

| | | |
|--------------------------------------|---------------------------------------|--|
| POINTS 2 | Compliance Date: Not Specified | Inspector Comments: Observed the main signage is not visible from the Spa Pool; All signs shall have clearly legible letters or numbers not less than 4 inches high, unless otherwise required, affixed to a wall, pole, gate or similar permanent structure in a location visible to all pool users. |
| | Not In Compliance | |
| Violation Reference - CCR 24 - 3120B | | |

Violation Description: All signs shall have clearly legible letters or numbers not less than 4 inches high, unless otherwise required, affixed to a wall, pole, gate or similar permanent structure in a location visible to all pool users. The following shall be posted:

- a) Maximum number of pool users permitted for each pool.
- b) "NO DIVING" at pools with a maximum water depth of 6 feet or less.
- c) Where no lifeguard service is provided, a warning sign shall be posted stating, "WARNING: NO LIFEGUARD ON DUTY." The sign also shall state in letters at least 1 inch high, "Children under the age of 14 shall not use pool without a parent or adult guardian in attendance."
- d) An illustrated diagram with text at least 1/4 inch high of artificial respiration and CPR procedures.
- e) The emergency telephone number 911 with numbers not less than 4 inches (102mm), the number of the nearest emergency services and the name and street address of the pool facility with numbers and text not less than 1 inch (25 mm) shall be posted.
- f) A warning sign for spa pools with "CAUTION" language.
- g) Where pools were constructed for which lighting was not required, a sign shall be posted at each pool entrance on the outside of the gate(s) stating, "NO USE OF POOL ALLOWED AFTER DARK."
- h) A sign shall be posted on the exterior side of gates and doors leading into the pool enclosure area stating, "KEEP GATE CLOSED" or "KEEP DOOR CLOSED".
- i) A sign in letters at least 1 inch high and in a language or diagram that is clearly stated shall be posted at the entrance area of a public pool which states that persons having currently active diarrhea or who have had active diarrhea within the previous 14 days shall not be allowed to enter the pool water.
- j) A sign in letters at least 1 inch high shall be posted that describes the requirements for wave pools.
- k) A sign shall be posted at each spray ground and be visible from any part of the spray ground that states, "CAUTION: WATER IS RECIRCULATED. DO NOT DRINK."

36K448 Equipment - Flow Meter

| | | |
|-----------------------------------|---------------------------------------|--|
| POINTS 2 | Compliance Date: Not Specified | Inspector Comments: Observed the flow meter is inoperative; Flowmeter shall be maintained in good repair, accurately displaying flowrate. |
| | Not In Compliance | |
| Violation Reference - CCR - 3125B | | |

Violation Description: A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow. Flowmeter shall be maintained in good repair, accurately displaying flowrate.



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

| | | |
|---|--------------------------|--|
| FACILITY NAME IRONWOOD / FAIRWAY | DATE 6/13/2014 | SIGNATURE  |
| LOCATION 11100 4TH ST, RANCHO CUCAMONGA, CA 91730 | | REHS Nick Thalasin |

36K462 Plumbing - Backflow Protection

| | | |
|--|--------------------------------|---|
| POINTS 2 | Compliance Date: Not Specified | Inspector Comments: Observed part of the output from the Separator bypasses the Plumbing Air Gap; All of the flow must pass through the legal Air Gap. |
| | Not In Compliance | |
| Violation Reference - CCR - 3141B, 3118B | | |

Violation Description: There shall be no direct connection between any potable water supply system and the pool or its piping system unless protected by a backflow prevention device in accordance with Chapter 6 of the California Plumbing Code.

There shall be no direct connection between the pool, its recirculation system or overflow drain to any sanitary sewer, storm drain or drainage system.

Potable water outlets with hose attachments shall be protected by a nonremovable hose bibb backflow preventer, a nonremovable hose bibb vacuum breaker, or by an atmospheric vacuum breaker.

Overall Inspection Comments

Fairway Spa Pool

Photo Attachments:

No Photo Attachments