





County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

(800) 442-2283

FACILITY NAME <b>FERNROCK ESTATES</b>				DATE <b>6/12/2014</b>	SIGNATURE	
LOCATION <b>872 SIERRA VISTA DR, TWIN PEAKS, CA 92391</b>				REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION <b>5/31/2015</b>	
MAILING ADDRESS <b>1420 N CLAREMONT BL STE 205-D, CLAREMONT CA 91711</b>				REHS <b>Breyanna Lyles</b>		
FA # <b>FA0001438</b>	PR # <b>PR0015696</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3620</b>	PROGRAM IDENTIFIER: Pool	
TIME IN <b>4:48 PM</b>	TIME OUT <b>5:33 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
					RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
					ACTION: 01 - NO FURTHER ACTION REQUIRED	

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**36K994 Reinspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: <b>Not Specified</b>	<b>Inspector Comments:</b> During the previous inspection the facility had a lack of chlorine in pool (measuring 0ppm).  During the follow-up inspection the facility has chlorine measuring 8.0ppm. The facility is now in compliance with required chlorine levels.
	Not In Compliance	
	Violation Reference - HSC	

**Violation Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**

No Photo Attachments