



**County of San Bernardino • Department of Public Health  
Division of Environmental Health Services  
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

**(800) 442-2283**

|  |                            |                                |                              |   |  |
|--|----------------------------|--------------------------------|------------------------------|---|--|
| FACILITY NAME<br><b>YMCA CAMP WHITTLE</b>                              |                            |                                |                              | DATE<br><b>6/25/2014</b>                  | SIGNATURE<br><i>[Signature]</i>  |
| LOCATION<br><b>31701 RIM OF THE WORLD DR, FAWNSKIN, CA 92333</b>       |                            |                                |                              | REINSPECTION DATE<br><b>Not Specified</b> | PERMIT EXPIRATION<br><b>12/31/2014</b>   |
| MAILING ADDRESS<br><b>625 S NEW HAMPSHIRE AV, LOS ANGELES CA 90005</b> |                            |                                |                              | REHS<br><b>Sierra Clayborn</b>            |  |
| FA #<br><b>FA0006890</b>   | PR #<br><b>PR0006584</b>   | SR #<br><b>Not Specified</b>   | CO #<br><b>Not Specified</b> | PE<br><b>3620</b>                         | PROGRAM IDENTIFIER: Pool<br>SERVICE: 001 - INSPECTION - ROUTINE                              |
| TIME IN<br><b>12:15 PM</b>   | TIME OUT<br><b>1:09 PM</b> | CONTACT<br><b>Not Captured</b> |                              |   | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP REQ<br>ACTION: 01 - NO FURTHER ACTION REQUIRED |

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

**96**

SCORE

|                   |
|-------------------|
| Ideal             |
| In Compliance     |
| Not in Compliance |



|                     |        |
|---------------------|--------|
| temperature (F)     | 83.0   |
| observed flow (gpm) | 260    |
| required flow (gpm) | 167    |
| volume (gal)        | 88,000 |
| area (sq ft)        | 2,600  |
| occupancy           | 131    |

**36K440 Enclosure - Non-Critical - Enclosure/Gates Non-Drowning Hazard**

|                                   |                                |  |
|-----------------------------------|--------------------------------|--|
| <b>POINTS</b><br><b>2</b>         | Compliance Date: Not Specified | Inspector Comments: Observed bottom rail of fence in 3 places needing welding. |
|                                   | Not In Compliance              | Repair immediately.  |
| Violation Reference - HSC - 3119B |                                |  |

**Violation Description:** The enclosure, doors and gates shall meet all requirements in the California Code of Regulations. Fencing/gates shall be maintained in good repair.

**36K474 Lighting - Adequate Lighting and Ventilation**

|  |                                |   |
|--|--------------------------------|---|
| <b>POINTS</b><br><b>2</b>                        | Compliance Date: Not Specified | Inspector Comments: Observed 2 pool lights out. Facility is already aware that they need repair. Observed no water in lights during inspection. |
|  | Not In Compliance              | Repair before next routine inspection.  |
| Violation Reference - SBCC - 3115B, 3106B, 3121B |                                |   |

**Violation Description:** Pools used at night shall be equipped with underwater lighting fixtures that will provide complete illumination to all underwater areas of the pool with no blind spots. Pool deck areas and emergency egress areas shall be provided with lighting so that persons walking on the deck can identify hazards. Lighting fixtures shall be aimed towards the deck area and away from the pool surface insofar as practical. Artificial lighting shall be provided at all spray ground pads which are used at night or which do not have adequate natural lighting so that all portions of the spray pad and deck may be seen easily.

Indoor pools, dressing rooms and toilet rooms shall be ventilated according to the requirements in Chapter 4 of the California Mechanical Code.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**

No Photo Attachments