



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME SAN BERNARDINO VALLEY COLLEGE				DATE 6/27/2014	SIGNATURE
LOCATION 701 S MT VERNON AV, SAN BERNARDINO, CA 92410				REINSPECTION DATE 12/27/2014	PERMIT EXPIRATION
MAILING ADDRESS 701 S MT VERNON AV, SAN BERNARDINO CA 92410				REHS John Babalola	
FA # FA0006489	PR # PR0014843	SR # Not Specified	CO # Not Specified	PE 3603	PROGRAM IDENTIFIER: Deep Pool
TIME IN 9:46 AM	TIME OUT 10:06 AM	CONTACT Not Captured			SERVICE: 001 - INSPECTION - ROUTINE
					RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED
					ACTION: 01 - NO FURTHER ACTION REQUIRED


RECREATIONAL HEALTH - Public School Pool / Spa

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

100

SCORE



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	228
volume (gal)	No Data
area (sq ft)	No Data
occupancy	169

36K952 Drained Pool or Spa Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: The pool is drained.
	Not In Compliance	
	Violation Reference - HSC	

Violation Description: An inspection was conducted at this time on a drained pool or spa. Contact DEHS prior to filling with water and/or operating.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:

No Photo Attachments