



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

(800) 442-2283

FACILITY NAME <b>CAMP SEELEY</b>				DATE <b>7/17/2014</b>	SIGNATURE <i>See Camp 001 7/17/14</i>
LOCATION <b>250 N HWY 138 , CRESTLINE, CA 92325</b>				REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION <b>12/31/2013</b>
MAILING ADDRESS <b>PO BOX 3372, CRESTLINE CA 92325</b>				REHS <b>Dior Porter</b>	
FA # <b>FA0006898</b>	PR # <b>PR0006571</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3620</b>	PROGRAM IDENTIFIER: Pool
TIME IN <b>10:15 AM</b>	TIME OUT <b>11:01 AM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - INSPECTION - ROUTINE
					RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED
					ACTION: 01 - NO FURTHER ACTION REQUIRED


**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

**100**  
SCORE

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	125
required flow (gpm)	141
volume (gal)	67,500
area (sq ft)	1,500
occupancy	75

**No Violations Cited**

**Overall Inspection Comments**

Observed directional arrows on the circulation system. Thank you for taking corrective action since your last inspection!

**Photo Attachments:**

No Photo Attachments