



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

(800) 442-2283

FACILITY NAME <b>AMADOR ON ROUTE 66</b>					DATE <b>7/21/2014</b>	SIGNATURE	
LOCATION <b>8090 CORNWALL, RANCHO CUCAMONGA, CA 91739</b>					REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION <b>8/31/2014</b>	
MAILING ADDRESS <b>1760 CALIFORNIA AV STE 101, CORONA CA 92881</b>					REHS <b>Nick Thalasinos</b>		
FA # <b>FA0015706</b>	PR # <b>PR0020872</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3623</b>	PROGRAM IDENTIFIER: Spa		
TIME IN <b>5:15 PM</b>	TIME OUT <b>5:45 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - INSPECTION - ROUTINE		
					RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP REQ		
					ACTION: 01 - NO FURTHER ACTION REQUIRED		

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

**98**

SCORE

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	28
volume (gal)	859
area (sq ft)	50
occupancy	5

**36K448 Equipment - Flow Meter**

POINTS <b>2</b>	Compliance Date: Not Specified	Inspector Comments: Observed the flow meter is not working correctly; Flowmeter shall be maintained in good repair, accurately displaying flowrate of 28 gpm.
	Not In Compliance	
	Violation Reference - CCR - 3125B	

**Violation Description:** A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow. Flowmeter shall be maintained in good repair, accurately displaying flowrate.

**Overall Inspection Comments**

Spa Inspection

Note: No E-Mail address available for this facility.

**Photo Attachments:**

No Photo Attachments