



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**




(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME RODEWAY INN					DATE 7/24/2014	SIGNATURE	
LOCATION 4075 E GUASTI RD, ONTARIO, CA 91761					REINSPECTION DATE Not Specified	PERMIT EXPIRATION 1/31/2015	
MAILING ADDRESS 4075 E GUASTI RD, ONTARIO, CA 91761					REHS Patrick Baccari		
FA # FA0008435	PR # PR0014171	SR # Not Specified	CO # Not Specified	PE 3620	PROGRAM IDENTIFIER: Pool		
TIME IN 12:55 PM	TIME OUT 1:10 PM	CONTACT Not Captured			SERVICE: 037 - POOL/SPA - BILLABLE INSPECTION SERVICE		
					RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP REQ		
					ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPENED		

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K430 Safety - Equipment/First Aid Kit

POINTS 2	Compliance Date: Not Specified	Inspector Comments: Rescue purposes with one or more rescue poles not less than 12 feet in length with body hooks. Replace broken body hook on pole.
	Not In Compliance	
	Violation Reference - CCR - 65539	

Violation Description: Every swimming pool shall be equipped for safety and rescue purposes with one or more rescue poles not less than 12 feet in length with body hooks, and one or more life rings having a minimum exterior diameter of 17 inches readily accessible for use. Such life rings shall have attached to them an 3/16 inch line long enough to span the maximum width of the pool. A first aid kit shall be provided at all swimming pools when required by DEHS.

Overall Inspection Comments

Cy 59.00 ppm
Ph 8.0
Cl 8.5

Pool and spa are hereby reopen at this time

Photo Attachments:

No Photo Attachments