



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

www.sbcounty.gov/dph/dehs

(800) 442-2283

| | | | | | | |
|---|-----------------------------|--------------------------------|------------------------------|---|---|--|
| FACILITY NAME CAMP CEDAR FALLS | | | | DATE 7/24/2014 | SIGNATURE | |
| LOCATION 3985 HWY 38 , ANGELUS OAKS, CA 92305 | | | | REINSPECTION DATE Not Specified | PERMIT EXPIRATION 12/31/2014 | |
| MAILING ADDRESS 39850 STATE HWY 38, ANGELUS OAKS CA 92305 | | | | REHS Robert Adams | | |
| FA # FA0007080 | PR # PR0004043 | SR # Not Specified | CO # Not Specified | PE 3620 | PROGRAM IDENTIFIER: Pool | |
| TIME IN 11:00 AM | TIME OUT 11:30 AM | CONTACT Not Captured | | | SERVICE: 001 - INSPECTION - ROUTINE | |
| | | | | | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP REQ | |
| | | | | | ACTION: 01 - NO FURTHER ACTION REQUIRED | |

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

98

SCORE

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|---------|
| temperature (F) | No Data |
| observed flow (gpm) | No Data |
| required flow (gpm) | 190 |
| volume (gal) | 64,500 |
| area (sq ft) | 1,500 |
| occupancy | 75 |

36K474 Lighting - Adequate Lighting and Ventilation

| | | |
|---------------------------|--|---|
| POINTS 2 | Compliance Date: Not Specified | Inspector Comments: Observed lights in the pool nonfunctional. Replace light bulb or repair light fixture. |
| | Not In Compliance | |
| | Violation Reference - SBCC - 3115B, 3106B, 3121B | |

Violation Description: Pools used at night shall be equipped with underwater lighting fixtures that will provide complete illumination to all underwater areas of the pool with no blind spots. Pool deck areas and emergency egress areas shall be provided with lighting so that persons walking on the deck can identify hazards. Lighting fixtures shall be aimed towards the deck area and away from the pool surface insofar as practical. Artificial lighting shall be provided at all spray ground pads which are used at night or which do not have adequate natural lighting so that all portions of the spray pad and deck may be seen easily.

Indoor pools, dressing rooms and toilet rooms shall be ventilated according to the requirements in Chapter 4 of the California Mechanical Code.

Overall Inspection Comments

Chlorine - 2.9ppm
 pH 7.4
 Cyanuric acid 25ppm.

Photo Attachments:
 No Photo Attachments