



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**



[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

(800) 442-2283

FACILITY NAME <b>OASIS APARTMENTS</b>				DATE <b>9/25/2014</b>	SIGNATURE	
LOCATION <b>500 W ARROW, UPLAND, CA 91786</b>				REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION <b>7/31/2015</b>	
MAILING ADDRESS <b>2400 N TENAYA WY UNIT 101, LAS VEGAS NV 89128</b>				REHS <b>Shannon Johnson</b>		
FA # <b>FA0008547</b>	PR # <b>PR0014086</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3620</b>	PROGRAM IDENTIFIER: Pool	
TIME IN <b>4:30 PM</b>	TIME OUT <b>4:42 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
					RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQUIR	
					ACTION: 03 - REINSPECTION REQUIRED	

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	31
volume (gal)	14,800
area (sq ft)	410
occupancy	21

**36K994 Reinspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> _____
	Not In Compliance	
	Violation Reference - HSC	

**Violation Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**36K444 Equipment - Recirculation Pump/Filter/Separation Tank**

<b>POINTS</b> <b>2</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed the separation tank to still be disconnected. _____
	Not In Compliance	
	Violation Reference - HSC - 3120B, 3132B, 3141B	

**Violation Description:** Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The pumps, filters and all related parts of the pool water purification system shall be kept in operation whenever the pool is available for use. All parts of the pool and related pool facilities and equipment shall be maintained in good repair.

The backwash from a diatomaceous earth filter shall discharge into a separation tank. The wastewater from the separation tank shall discharge into a sanitary sewer or other disposal system acceptable to the local wastewater agency.

The direction of flow for the recirculation equipment shall be labeled clearly with directional symbols such as arrows on all piping in the equipment area.

**Overall Inspection Comments**

A charged follow up inspection will be conducted on 10-16-14 to ensure repairs have been conducted to the separation tank and it is functioning as it should be. Failure to comply will result in another charged inspection.

**Photo Attachments:**  
No Photo Attachments