



COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REPORT

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME ALTA LOMA HIGH SCHOOL				DATE 10/6/2014	SIGNATURE	
LOCATION 8880 BASELINE RD, RANCHO CUCAMONGA, CA 91701				REINSPECTION DATE Not Specified	PERMIT EXPIRATION	
MAILING ADDRESS 276 N SECOND AVE UPLAND, CA 91786				REHS Bennetta Betbadal		
FA # FA0006436	PR # Not Specified	SR # SR0065247	CO # Not Specified	PE 3712	PROGRAM IDENTIFIER: None	
TIME IN 7:30 AM	TIME OUT 9:20 AM	CONTACT Not Captured			SERVICE: 025 - PLAN REVIEW	
				RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED		
				ACTION: 55 - PLANS APPROVED		

RECREATIONAL HEALTH PLAN CHECK - Plnck Pool New 1,000-Up SqFt

37K980 Plans - Plan Review Approved

Compliance Date: **Not Specified**
Not In Compliance
Violation Reference - **HSC**

Inspector Comments:
Plan is approved for new pool at the high school. Existing 2 pools will be demolished to build one larger pool.

Violation Description: Plans have been approved and this correction sheet is a part of the approved plans.

37K010 Ancillary - Drinking Fountain

Compliance Date: **Not Specified**
Not In Compliance
Violation Reference - **CCR 24 - 3116B**

Inspector Comments:

Violation Description: Provide a drinking fountain within the pool vicinity.

37K011 Ancillary - Finishes

Compliance Date: **Not Specified**
Not In Compliance
Violation Reference - **CCR 22 - 65505**

Inspector Comments: Ensure that base covers in restroom and showers area has 3/8" radius.

Violation Description: Provide a finish schedule for the floor, wall, and ceiling surfaces in the restrooms and shower.

37K016 Ancillary - General - Cold

Compliance Date: **Not Specified**
Not In Compliance
Violation Reference - **CCR 24 - 3115B.4.1**

Inspector Comments: Showers by the pool area shall have HOT and Cold water. Plans shows only cold line. Ensure to add the HOT water line as well. Correction will be verified PRIOR TO FINAL INSPECTION.

Violation Description: Provide the showers and lavatories with hot and cold running water.

37K017 Ancillary - General - Floor

Compliance Date: **Not Specified**
Not In Compliance
Violation Reference - **CCR 24 - 3115B.3.1**

Inspector Comments: 3114B.3 Deck slope. The pool's deck surface shall have a slope of no less than 1 percent (1/8 inch per foot) but no more than 2 percent (1/4 inch per foot) away from the pool to a deck drainage system and shall be constructed and finished to prevent standing water.

Violation Description: Floors shall be slip resistant and shall be sloped not less than one quarter (1/4) inch per foot to a floor drain.

37K060 Enclosure - Closure

Compliance Date: **Not Specified**
Not In Compliance
Violation Reference - **CCR 24 - 3118B.2**

Inspector Comments:

Violation Description: Gates and doors shall be equipped with self-closing and self-latching devices. The self-latching device shall be designated to keep the gate or door securely closed.



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME ALTA LOMA HIGH SCHOOL	DATE 10/6/2014	SIGNATURE
LOCATION 8880 BASELINE RD, RANCHO CUCAMONGA, CA 91701	REHS Bennetta Betbadal	

37K066 Enclosure - General - Chain Link

Compliance Date: Not Specified
Not In Compliance
Violation Reference - CCR 24 - 3118B.1

Inspector Comments:

Violation Description: Chain link may be used provided that the openings are not greater than one and three quarter (1 3/4) inches measured horizontally.

37K067 Enclosure - General - Climb

Compliance Date: Not Specified
Not In Compliance
Violation Reference - CCR 24 - 3118B.3

Inspector Comments:

Violation Description: The enclosure shall be designed and constructed so that it cannot be readily climbed by small children. Horizontal and diagonal member designs, which might serve as a ladder for small children, are prohibited. Horizontal members shall be spaced at least 48 inches apart.

37K481 Enclosure - General - Stone

Compliance Date: Not Specified
Not In Compliance
Violation Reference - CCR 24 - 3118B

Inspector Comments:

Violation Description: Stone columns, walls, etc. that are part of the pool enclosure (fence) must be a minimum 5 feet tall, smooth and non-climbable

Overall Inspection Comments

Surface Area: 9,038 sq ft
Capacity: 491,322 gallons
Flow Rate: 1,252 gpm

Main drain Suction: 10" @ 6 fps 1475 gpm
Gutter Suction Line: 10" @ 6 fps 1475 gpm
Return Line: 10" @ 8 fps 1966 gpm

Circulation Pump: Paco 6015.7 25 HP 1340 gpm
Fillters: EKO 3 High Rate Sand 42-225-4 90 sq ft 1350 gpm
Chlorinator: LMI Liquid chlorine SD43-88P 288 gal/day
Drain Covers: Lawson FI-SG-1836-15 18" x 36"

Solar Pump: Intelliflo VS + SVRS 3HP 135 gpm
Solar Suction Line: 3" @ 6 fps 138 gpm
Solar Return: 3" at 8 fps 184 gpm

Photo Attachments:
No Photo Attachments