



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REPORT**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

(800) 442-2283

FACILITY NAME <b>UPLAND VISTA</b>				DATE <b>12/2/2014</b>	SIGNATURE	
LOCATION <b>1532 CORTE HACIENDA , UPLAND, CA 91786</b>				REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION	
MAILING ADDRESS <b>1547 LOS ANGELES AVE VENTURA, CA 93004</b>				REHS <b>Bennetta Betbadal</b>		
FA # <b>FA0008524</b>	PR # <b>Not Specified</b>	SR # <b>SR0066243</b>	CO # <b>Not Specified</b>	PE <b>3716</b>	PROGRAM IDENTIFIER: <b>None</b>	
TIME IN <b>1:30 PM</b>	TIME OUT <b>2:57 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: <b>025 - PLAN REVIEW</b>	
				RESULT: <b>01 - CORRECTIVE ACTION NOT REQUIRED</b>		
				ACTION: <b>55 - PLANS APPROVED</b>		

**RECREATIONAL HEALTH PLAN CHECK - Plnck Pool Minor Remodel - all**

**37K980 Plans - Plan Review Approved**

Compliance Date: **Not Specified**  
Not In Compliance  
Violation Reference - **HSC**

**Inspector Comments:** Plan is approved for resurfacing of the pool and spa with Aqua Glass fiberglass lining. New waterline tiles, trim tiles and break line. New hand rails, depth markers, and splitting the main drain for the pool.

**Violation Description:** Plans have been approved and this correction sheet is a part of the approved plans.

**37K084 Equipment - Disinfection - Size**

Compliance Date: **Not Specified**  
Not In Compliance  
Violation Reference - **CCR 24 - 3133B.1**

**Inspector Comments:** Chlorinator shall be able to provide 8.25 lb of chlorine per day for the pool. Noted Pentair Rainbow 300 chlorinator is small and shall be upgraded to an efficient one.

**Violation Description:** The disinfectant feeder shall be capable of supplying not less than the equivalent of 3 pounds of chlorine per day per 10,000 gallons of pool water capacity.

**Overall Inspection Comments**

"ALL PREEXISTING PLUMBINGS, AND EQUIPMENT FOR POOL AND SPA ARE SUBJECT TO FIELD VERIFICATION AND APPROVAL, AND SHALL BE IN COMPLIANCE WITH POOL CODE".

**Pool Info:**

Pool Surface: 720 sf  
Pool Capacity: 27,500 gallon  
Pool Flow Rate: 57-76 gpm  
Pool Occupancy: 36 bathers  
Suction Line: 2" 84 gpm at 8 fps  
Return Line: 1 1/5" 43 gpm copper pipe  
Pump: Pentair SVRS 3 HP 76 gpm  
Filter: Pentair ?  
Chlorinator: Pentair Rainbow 300  
Drain Covers: Paramount SDX 200gpm floor, 192 gpm wall

**Spa Info:**

Spa Surface: 80 sf  
Spa Capacity: 1350 gallons  
Spa Flow Rate: 45 gpm  
Spa Occupancy: 8 bathers  
Suction Line: 2" 84 gpm at 8 fps  
Return Line: 1 1/5" 43 gpm copper pipe  
Recirculation Pump: Pentair WFE-3 3/4 HP 55 gpm  
Filter: Pentair ?  
Chlorinator: Pentair Rainbow  
Booster Pump: Pentair WFE-8 110 gpm

**Photo Attachments:**  
No Photo Attachments