



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME COGUA AQUATICS				REINSPECTION DATE Not Specified	INSPECTOR Richard Mejia	DATE 12/23/2015
LOCATION 14523 RAMONA AV, CHINO, CA 91710				PERMIT EXPIRATION	IDENTIFIER: None	
TIME IN 10:22 AM	TIME OUT 12:14 PM	FACILITY ID FA0028829	RELATED ID CO0052995	PE 3620	SERVICE: 004 - COMPLAINT - INITIAL RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED	




RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K522 Safety – Critical – Unsafe or hazardous conditions **⚠ CRITICAL ⚠**

POINTS 5	Compliance Date: Not Specified	Inspector Comments: a. Secure Stair handrail's (loose). b. Distangle rope to life ring.
	Not In Compliance	
	Violation Reference - HSC - 65545	

Violation Description: A public pool that is maintained or operated in a manner that creates an unhealthful, unsafe, or unsanitary condition may be closed by the enforcing agent.

36K597 Construction - Pool shell tiles and surface

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Repair coping grouts around the pool (deteriorated).
	Not In Compliance	
	Violation Reference - CCR - 3108B	

Violation Description: The finished pool shell shall be lined with a smooth waterproof interior finish that will withstand repeated brushing, scrubbing and cleaning procedures. The interior pool finish shall completely line the pool to the tile lines, coping, or cantilevered deck.

- The finish color shall be white except for the following which shall be of contrasting color:
- Lane and other required pool markings described in Section 3110B of the California Code of Regulations; and
 - The top surface edges of benches in spa pools; and
 - The edge of pool steps; and
 - Tiles installed at the waterline; and
 - Tiles installed at the 4 1/2-foot (1372 mm) depth line.

Overall Inspection Comments



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

<small>FACILITY NAME</small> COGUA AQUATICS	<small>DATE</small> 12/23/2015
<small>LOCATION</small> 14523 RAMONA AV, CHINO, CA 91710	<small>INSPECTOR</small> Richard Mejia

12/17/2015 COMPLAINT INVESTIGATION CONDUCTED BY: MICHAEL VILLARAZA, COUNTY OF LOS ANGELES ENVIRONMENTAL HEALTH.

pH: 7.8
Cl: 5+ ppm

Also noted on inspection report: Secure stair hand rails (loose).

RETAIN COPY OF INSPECTION REPORT.

OPERATOR / GIOVANNI COGUA

ENTERED ON Envision Connect by: RICHARD MEJIA

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0