



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME RODEWAY INN			REINSPECTION DATE Not Specified	INSPECTOR Monica Lucey	DATE 12/30/2015
LOCATION 4075 E GUASTI RD, ONTARIO, CA 91761			PERMIT EXPIRATION	IDENTIFIER: None	
TIME IN 10:00 AM	TIME OUT 10:30 AM	FACILITY ID FA0008435	RELATED ID CO0053071	PE 3623	SERVICE: 004 - COMPLAINT - INITIAL RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 01 - NO FURTHER ACTION REQUIRED

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

No Violations Cited

Overall Inspection Comments

Field investigation revealed:
Observed: Pool is closed temporarily until maintenance crew shows up to clean it. Per employee, it has been closed since Christmas. Pool and hot tub are in the same area. Observed dirty pool with debris on the bottom.
No further action taken.

Inspector: Benjamin Montes, LACo
Inputted by: Monica Lucey, LACo

Signature(s) of Acknowledgement

NAME:
TITLE:
Total # of Images: 0