



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REPORT

FACILITY NAME ALTA LOMA HIGH SCHOOL		DATE 9/4/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 8880 BASELINE RD, RANCHO CUCAMONGA, CA 91701			INSPECTOR Tin Nguyen	
MAILING ADDRESS 276 N SECOND AVE UPLAND, CA 91786			IDENTIFIER: None	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT			SERVICE: 126 - PLAN CHECK FIELD INSPECTION	
TIME IN 11:22 AM	TIME OUT 12:26 PM	FACILITY ID FA0006436	RELATED ID SR0065247	PE 3712
RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU				
ACTION: 03 - REINSPECTION REQUIRED				

RECREATIONAL HEALTH PLAN CHECK - PInCk Pool New 1,000-Up SqFt

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

37K994 Reinspection

Compliance Date: Not Specified

Not In Compliance

Reference - HSC

Inspector Comments:

-A follow-up inspection was conducted at facility to verify the following:

1. Gates to be installed with mesh to prevent climbing
2. "Keep gate closed" signs on all gates to pool
3. Phone number to nearest emergency agency
4. Directional arrows on pool recirculation pumps
5. Hot water at shower stalls in pool area

Upon inspection, observed four items mentioned above in compliance, except sign with phone number of nearest emergency agency. Provide phone number on pool sign of nearest emergency agency in pool area.

NOTE:

-A future re-inspection will be conducted for completion of two restrooms, located outside pool area. Operator will contact Division of Environmental Health Services (DEHS) in approximately a month for a follow-up inspection of two restrooms.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Kevin Jones
TITLE: Person in Charge

Total # of Images: 0